

MAY 0 5 1997

Signed by \_

Surveyor's Michigan License No. 39091

## LAND CORNER RECORDATION CERTIFICATE

		Filing Requi	rement of Act 74, Mich	. P.A. 1970			
For corners in  Bai	COMMIS	SION  Located In:	Corner Code #	DAY OF A.M. A	ED FOR RECORD THIS DECEMBER, 1996 AT ND RECORDED IN LIB	10:30 ER 4	
1. Public Land S	urvey	T <u>51N</u> R <u>33W</u> T R T R T R	F-11	4	D CORNER RECORDATI S ON PAGES 734-735		
in Section 3. Miscellaneous	. Property Controlling S T R in Section S T R				BARAGA COUNTY REGISTER OF DEEDS  Register of Deeds Stamp & File Number		
4. Lot No 5. Private Claim	, Recorded	Plat		1 A B	C D E F G H I J	K L M	
state that under req and 2 above were in of survey instruction a decree of a Court conformance with t	uirements of P.A. 7 n conformance with ns of the United Stat of Law and /or tha he rules of the Mich	<ol> <li>Michigan P.A. of 1970, regulations and rules there es Department of the Inter t the corner points mentio</li> </ol>	nber , 19 96 d the corner points mentioned in fore as required in the curren ior, Bureau of Land Managern ned in lines 3, 4 and 5 above ors or by a Decree of a Court ressed below:	in lines 1 4 7 - 7 - 1	8 9 10 1 17 16 15 1	1 12-	
NOTE: Not more to on this ce		n the same town and range	e, may be recorded	9 10 30 11	29 28 27 2	6 -25	
A. Description of original monument and accessories and/or subsequent restoration:					32 33 34 3	5 36	
F-11; One-qua	rter Corner co	mmon to Sections 2	28 and 33, T51N, R3	3W;	APPROVED LAND COR P.A. 345 OF 1990 Baraga County	NER	
See back	of form.				2/1		
B. Description of	f corner evidence	found and/or method a	ipplied in restoring or rees	tablishing corner:	12-18-26	<del></del>	
F-11; One-qua	rter Corner co	mmon to Sections	28 and 33, T51N, R3	3W;			
in 1981	. The corner i	s located 14.0 feet	ent box as recovered north of the physical e best available evide	centerline of M-	a, PS 38. This corner on of the original corn	ier.	
C. Description of	of monument for (	corner and accessories (	established to perpetuate I	ocating the position	of the corner:		
F-11; One-qua	rter Corner co	mmon to Sections	28 and 33, T51N, R	33W;			
Found a	a 1" iron rod ir	a monument box.					
Set 7" Set 7" Set 7" Set 7"	spike SW/s spike W/sid	de Power Pole e Power Pole	N55°E S73°E S18°W N31°W	45.95' 146.01' 54.50' 29.80'	SATE OF MICHIGAN		
All of the	ne above acce	ssories are marked	with a vertical red pa		MICHAEL D. MILESKI PROFESSIONAL SURVEYOR NO. 39091	SYOR A	
	W	1					

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971

A. Description of original monument and accessories and/or subsequent restoration:

F-11; One-quarter Corner common to Sections 28 and 33, T51N, R33W;

Originally established during U.S. Survey conducted by Harvey Mellen, D.S. in 1845 and monumented with a cedar post witnessed by a

 Cedar
 7
 N59°W
 14 lks.

 Hemlock
 8
 N36°E
 25 lks.

This corner was recovered in 1981 by Brian Taavola, PS #21583 as being monumented with a 1" iron pin in a monument box as per Michigan Department of Transportation Plans, File #N-23-A-3, 1956. Refer to LCRC prepared by Mr. Taavola and recorded in Liber 4 on page 14 of the Baraga County Land Corner Records. Mr. Taavola did not remonument the corner but noted the following accessories:

Tel. Pole S15°W 54.53'
Power Pole N60°E 45.93'
Power Pole N30°W 29.84'
7" Spruce S35°E 70.93'

Mr. Taavola's corner was accepted by the BLM during the course of their 1984 survey of T51N, R33W.

SURVEY & SEMONUMENTATION

MAY 0 5 1997

COMMISSION