

AUG 05 1994

COMMISSION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in
Baraga
 (County)

Located In: Corner Code --#

- | | | |
|---------------------------------------|---------------------------|-------|
| 1. Public Land Survey | T <u>51N</u> R <u>33W</u> | F-13 |
| | T _____ R _____ | _____ |
| | T _____ R _____ | _____ |
| | T _____ R _____ | _____ |
| 2. Property Controlling in Section | S _____ T _____ R _____ | _____ |
| | S _____ T _____ R _____ | _____ |
| 3. Miscellaneous Property in Sec. | S _____ T _____ R _____ | _____ |
| | S _____ T _____ R _____ | _____ |
| 4. Lot No. _____, Recorded Plat _____ | | |
| 5. Private Claims _____ | | |

RECEIVED FOR RECORD THIS 2ND DAY OF AUGUST, A.D. 1994 AT 9:00 A.M. AM RECORDED IN LIBER 4 OF LAND CORNER RECORDATION ON PAGE 485.

Dennis R. Destrampe
 BARAGA COUNTY REGISTER OF DEEDS
 Register of Deeds Stamp & File Number

I, Dennis R. Destrampe in a field survey on December 17, 1993, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

A. Description of original monument and accessories and/or subsequent restoration:
 Wood Post Original corner not found. No record of subsequent restoration.
 Hemlock 8 N37E 49
 Cedar 6 N58W 22

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
 Found 1" iron pipe with 3½" aluminum cap 6" above ground. Cap reads MICH DEPT OF NATURAL RESOURCES, T51N, R33W, 1/4 33, 4/8/77, RLS 19006.
 Found witnesses: 10" Aspen N12W 11.72' (Nail & tag "RLS 24591")
 Telephone Pole North 38.59' (Nail & tag "RLS 24591")
 (Nail & tag "MDOT RM)

APPROVED LAND CORNER
 P.A. 345 OF 1990
 Baraga County



12-1-93
DL

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
 Corner accepted as found. Rewitnessed.

Witnesses: 7" Balsam N23E 37.88' (Nail & tag "UPEA 18983" set)
 USGS B.M. C-48 S69E 66.27'
 9" Spruce N78W 79.65' (Nail & tag "UPEA 18983" set)
 20" W. Pine N24W 61.21' (Nail & tag "UPEA 18983" set)

All of the above new bearing trees are scribed "NBT".

Signed by Dennis R. Destrampe Date June 17, 1994
 Surveyor's Michigan License No. 18983