SURVEY & REMONUMENTATION

MAY 0 5 1997

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

₩£12.€ 0	v v (40)	Filing Requir	ement of Act 74, N	Mich. P.A. 1970					
	MISSION			R	RECEIVED	FOR RECOR	RD THIS	20TH	
Barag (County)	<u>a</u>	ocated In:	Corner Code #	· #	M. AND	ECEMBER, 1 RECORDED	IN LIBE	R 4	
TR						CORNER REC ON PAGES			
2. Property Controll	,	TR TR TR		_	The	ELN THE	Late	- N	
in Section 3. Miscellaneous	S ·	Γ R Γ R		B	ARAGA\ C	DUNTY REGI	STER OF	DEEDS	
Bronarty in San S T D						gister of Deeds Stamp & File Number			
4. Lot No.					A B C	D E F G	H I J	K I. M	
5. Private Claims _					2 6	5 4	-3-2-		
, Michael Milesk		urvey on <u>November</u>		nereby state	3 - 7		10-11-		
above were in conforma	ance with regulations	s and rules therefore a	s required in the curre	ent manual of	5				
survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law;						17-16-	-1,5 -1,4	13-	
established, re-establishe					7		+ + +		
NOTE: Not more than on this certific		ame town and range,	may be recorded	9	9 -19	20 21 -	-22 -23	24	
A Description of ari		.dii/-			0 30	29 -28	-2726	25-	
A. Description of orig	jinai monument an	u accessories and/o	r subsequent restora	ation:	1	+ + + + + -	+ -		
G-1; Closing Corn	er common to	Sections 3 and 4	, T51N, R33W;		31	32	34 -35	36	
See back of t	orm.			*		PPROVED LAI P.A. 345 C	ÖF 1990	R	
3. Description of co-	rner evidence foun	d and/or method ap	olied in restoring or i	reestablishing cor	ner:	Baraga C	County		
G-1; Closing Corner common to Sections 3 and 4, T51N, R33W;						12-18-96			
J-1, Closing Com	a common to .	Sections 5 and 4	, 1911, N33W,					_	
the east and	west. Corner per the physical ce	ed on line and at position falls in ti enterline of Bear	ne centerline of a	a railroad 2.4	feet west	of the eas	t rail and	4.5	
Description of mo	nument for corner	and accessories est	ablished to perpetua	ate locating the p	osition of t	he corner:			
G-1; Closing Corne	er common to S	Sections 3 and 4	, T51N, R33W;			*****	MANA		
) x 36" galvani 18" below the	zed iron pipe wit e road surface.	h 2" aluminum d	cap stamped		MICHAL		1	
i) Set 7" s	pike NW/sid	e 14" White S	oruce N38°E	123.75	, [*	MILES PROFESS			
ii)	NW cor			22.60'	, ic	SURVE No.	23.	Į	
iii) Set 7" s iv) Set 7" s	•	Power Pole 12" Red Mag	S74°W N80°W		` \	PROFESS SURVE No. 3909		F	
v) 3et / s	hive Maine	S.C.Sec. 33		15.27'	•	PROFESS	ONAL		

(i) and (iv) are marked with upper and lower blazes. The lower blaze is scribed "NBT". Both blazes as well as a band around the tree at the upper blaze were painted red.

(v) The standard corner of sections 33 and 34, T52N, R33W is monumented with a 1" (l.D.) \times 36" galvanized iron pipe with 2" aluminum cap stamped as to location.

Date 18 Dec 1990

LIBER 4 PAGE 736

A. Description of original monument and accessories and/or subsequent restoration:

G-1; Closing Corner common to Sections 3 and 4, T51N, R33W;

Originally established during U.S. Survey conducted by Harvey Mellen, D.S. in 1845 and monumented with a wood post witnessed by a

47 lks. 32 lks.

Yellow Birch 18

S41°E S10°W

During the course of a survey conducted by Stephen Douglas of the Bureau of Land Management from 10 May 1984 to 10 November 1984 and approved 23 September 1985, this corner was considered lost. The BLM neither found nor set a monument.

SURVEY & REMONUMENTATION

MAY 0 5 1997

COMMISSION