STATE OF MICHIGAN DEPARTMENT 0F **NATURAL RESOURCES**

LAND CORNER RECORD

Baraga

			Baraga	COUNTY
		T	52 N	R
DESCRIPTION OF CORNER _	North 1/16 corner between Se	ecti	ons 34 and 35	5
CORNER MONUMENT 1"	I.D. x 36" iron pipe with 4"	alu	minum cap.	
DATE MONUMENT PLACED AND	WITNESSED June 24, 1970			
WITNESSES TO CORNER	Hemlock 16 N84°E (mag.)	43.2	ft. "1/16S,	BT''
N	Red Maple 5 N33°E (mag.)	45.9	ft. "1/16S,	BT"
35	AND			
CIRCLE CORNER REGISTERS	:D			

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Not established in original survey.

No evidence that the corner had been established previously.

Found a location tag on a 4" maple S21°W .935 ch. from corner, but no monuments.

Corner established on line between section corner 20.034 ch. north and 1/4 corner 20.034 ch. south.

SURVEYOR'S SEAL

SIGNED

DATE September 28, 1971

DISTRIBUTION:

Arthur O. Enger

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing

R 4047 Rev. 10/68