STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

LAND CORNER RECORD

	Daraga	COUNTY
	T	R
DESCRIPTION OF CORNER Section Corner 26, 27, 34,		
Replaced the found iron pipe with 4" aluminum	ith a 1" I.D. x 3 n cap.	6''
DATE MONUMENT PLACED AND WITNESSED June 24, 197	70	
NITNESSES TO CORNER Red Maple 18 S30°E (mag.)	5.7 ft. "S35,	NBT''
Red Maple 11 S11°W (mag.)	40.3 ft. "S34,	NBT"
Sugar Maple 7 N35°E (mag.)	6.1 ft. "S26,	NBT"
AND Y. Birch 10 N38°W (mag.) CIRCLE CORNER REGISTERED	17.0 ft. "S27,	NBT"

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Found a 1 3/4" O.D. x 36" iron pipe in place, apparently long accepted and used as the corner by local land owners. The position checks well with river crossings to the south and east and with other corners around Sec. 35. Many old blazed trees in vicinity; blazed lines to E, W, and S intersect here. Ford Motor Company location tag bearing date 3/30/49 on tree to SE. Found no evidence of original post or its accessories.

Corner accepted as found.

SURVEYOR'S SEAL

DISTRIBUTION: SIGNED

REGISTERED LAND SURVEYOR

DATE September 28, 1971

Arthur O. Enger

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing