SURVEY & REMONUMENTATION

FEB 2 3 1998

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in				:						
Baraga (County)	Local	ted In:	Corner Code #							S 30T
(account)					30 A					97 AT
Public Land Survey	T_52	N R 33W	B-1 *	10:	ER 4	·M·	AND.	COD	KUEL) 1N
		TR				ינט מחזים	באנה האינה	AVGU.	NER.	PAGE
	<u>T</u>	<u>R</u>		797				الماليون مستم ما		PAGE
2. December Contaction	Ι	R		71	ild	N	us			
2. Property Controlling in Section	> !	R			<u> </u>			•		
3. Miscellaneous	S	R R		BARAC	SA CO	UNIY	REGIS	TER C	F DE	EDS
Property in Sec.	S T	R								
respectly in Oct.	·		,,	·	Regist	er of D	eeds St	amp &	File N	mber
				٠						
4. Lot No, Reco	orded Plat		•	- '						
5. Private Claims				1	A B C	D 1	E F G	_ R _ 7	J	K L M
				2	<u> </u>	5	4	<u> </u>		1-1-
1 Michael Milanti	: e.u			3 :		_		;	_ [·
that under requirements of P.A. 7			ember , 19 97 do hereby			0		10	.i	. 12
above were in conformance with regulations and rules therefore as required in the current manual of							7		1	12-
survey instructions of the United	States Departmen	nt of the Interior,	Bureau of Land Management o	orbya 5;	Ι,		-		1	
decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law;				fLaw;	_18	17	16	—1 5—	—14—	13-
established, re-established, monu-	mented, recovered	d, found as expre	ssed below:	7			 			†
NOTE: Not more than 2 corner	n all in the same	tour and man	more he weeneded	8	_19_	20	<u> </u>	22	23	24
on this certificate.	s, and the same	town and range,	may be recorded	; 9				`		·
				10	30	29	28-	_27_	26	26
A. Description of original monument and accessories and/or subsequent restoration:					أحأ			i	-:	
				11		ا				
B-1; North One-quarter (Corner Section	n 6, T52N,	R33W;	12	-31-	-32	5 5	—5 4— ÷		36-
				13~	:				.	
			inducted by William Bu	irt,	API	PROVE	CIAND	CORN	ER	
	nonumented	with a wood	d post witnessed by a			P.A. 3	45 OF	1990		
Black Ash 8	N60°W	64 lks.				Bara	ga Cou	nty		
and a		•				10	4:4	7		
Black Ash 16	N83°E	232 lks.		•		11	1			
					•	/ /	/			
The north line of se	ection 6 was	run by the N	viichigan Department o	of Natural	Resou	rces i	n 197	7.		

The north line of section 6 was run by the Michigan Department of Natural Resources in 1977. The field notes of this survey do not mention an existing monument at the N¼ corner of section 6.

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- B-1; North One-quarter Corner Section 6, T52N, R33W;

This corner was considered lost and reestablished on line at the proportionate distance between the northwest corner of section 6 and the north one-quarter corner of section 5. The northwest corner of section 6 was reestablished by double proportionate measure in 1977 by Keith Sackett, P.S. of the Michigan Department of Natural Resources. The north one-quarter corner of section 5 is an original corner perpetuated by Keith Sackett, P.S. in 1977.

- IC. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- B-1; North One-quarter Corner Section 6, T52N, R33W;

Set a 1" (I.D.) x 72" galvanized iron pipe with cap stamped as to location projecting 6" above ground.

Set 7" spike	SE/side	8" Black Ash	N71 °E	3.72'
Set 7" spike	NE/side	6" Black Ash	S38°E	25.75'
Set 7" spike	E/side	7" Black Ash	S12°W	16.71'
Set 7" spike	SE/side	8" Black Ash	S53°W	21.93'
Set 7" spike	S/side	6" Yellow Birch	N84°W	19.84
Set 7" spike	W/side	6* Red Maple	NO2°W	50.42
	6' Steel fen	South	1.5'	

All of the above new bearing trees are marked with upper and lower blazes. The lower blaze is scribed "NBT". Both blazes and a band around the tree at the upper blaze were painted red.

*This corner is also B-13 of T53N, R33W.

LIBER 4 PAGE 793



-gned by will make

· ~