LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

	Filing Requ	uirement of Act 74, Mich.	. P.A. 1970
For corners in Baraga	Located In:	Corner Code #	RECEIVED FOR RECORD THIS 14TH DAY JANUARY A. D. 1999 AT 10:30 A. M.
(County)		33.7.3.3.4.3.4.4.4.4.4.4.4.4.4.4.4.4.4.4	RECORDED IN LIBER 5 OF LAND CORNE RECORDATION RECORDS ON PAGE 25.
1. Public Land Survey	T_52N R_33W T R T R T B	<u>E-11</u>	BARAGA COUNTY REGISTER OF DEEDS
2. Property Controlling S in Section S	TR TR		
3. Miscellaneous S Property in Sec. S	TR		Register of Deeds Stamp & File Number
4. Lot No, Record 5. Private Claims	ed Plat		A B C D E F G H I J K L
I, Michael Mileski, ithat under requirements of P.A. 74, above were in conformance with resurvey instructions of the United Stadecree of a Court of Law and for the conformance with the rules of the M	Michigan P.A. of 1970, the of gulations and rules therefor tes Department of the Interi- nat the corner points mention	corner points mentioned in lines re as required in the current moor, Bureau of Land Management oned in lines 3, 4 and 5 above	1 and 2 4 -7 8 9 10 11 -12 anual of tor by a 5 were in 6 -10 17 16 16 17
established, re-established, monumer NOTE: Not more than 2 corners, a on this certificate.	nted, recovered, found as ex	pressed below:	7 8 -19 -20 -21 -22 -23 -24 -
A. Description of original monu	ment and accessories and	d/or subsequent restoration:	10 30 29 28 27 26 25
E-11; Section Corner com	12 31 32 33 34 35 36		

Originally established during U.S. Survey conducted by William Burt, D.S. in 1849 and monumented by a 12" diameter maple witnessed by a Hemlock 24 N28°W 17 lks. and a Hemlock 15 S12°E 21 lks. On page 4 of the Baraga Township Highways Journal, the centerline of the Keweenaw Bay and Otter Lake Road (presently known as Sturgeon Road) was described as passing through this corner (entry dated 30 August 1900). On page 11 of the Highways Journal, Napoleon Gagner Road (presently known as Jarvi Road) was designated to commence at this corner (entry not dated).

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

APPROVED LAND CORNER P.A. 345 OF 1990 Baraga County A

E-11; Section Corner common to Sections 28, 29, 32 and 33, T52N, R33W;

Found a 1" x 24" iron rod at the physical intersection of Sturgeon Road and Jarvi Road. This monument was found 24 inches below the top of the asphalt. An old, mostly down, fence runs south from this monument a distance of 4800 feet to the north edge of Kelsey Creek. This fence was found to be within five feet of a direct line connecting this monument to the SE corner of section 32 (an original corner) at all nine points located. Accepted as the best available evidence as to the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

E-11; Section Corner common to Sections 28, 29, 32 and 33, T52N, R33W;

Replaced found monument with a 1" x 36" galvanized iron pipe with cap. This monument was set 12 inches below the asphalt. The 8 inch diameter asphalt opening was filled with 6 inches of MDOT-furnished CP-7 material. A 7" spike was set at the surface directly above the iron pipe monument.

Set 7" spike	E/side	7" Aspen	N37°E	99.01
SW corner of	metal-sided	addition to fr. hse.	S40°E	177.71'
Set 7" spike	W/side	11" Apple	S04°W	40.05
Set 7" spike	SE/side	Power Pole	S35°W	37.76'
•	6' Steel fer	nce post w/ yellow sign	South	35.0'

Only the aspen NBT was blazed, scribed and painted. The power pole was marked with a vertical red paint stripe. The apple NBT was not marked or painted.

Signed by _____



25

PAGE