LAND CORNER RECORDATION CERTIFICATE

a take in the land	Filing Requirement of Act 74, Mich. P.A. 1970				
For corners in Baraga (County)	Located in:	Corner Code #	RECEIVED FOR RECORD THIS 14TH DAY JANUARY A. D. 1999 AT 10:30 A. M. AND RECORDED IN LIBER 5 OF LAND		
1. Public Land Survey	T <u>52N</u> R <u>33W</u> T R T R	#17) East MC between B-9 and C-9	35. Corner recordation records on page 35. Corner recordation Records on page 35.		
Property Controlling in Section S Miscellaneous Property in Sec. S	5 T R S T R		BARAGA COUNTY REGISTER OF DEEDS		
4. Lot No, Record 5. Private Claims	ded Plat		A B C D E F G H I J K L M		
that under requirements of P.A. 74, above were in conformance with n	Michigan P.A. of 1970, the congulations and rules therefore	as required in the current man	and 2 4 7 8 9 10 11 12 ual of		
survey instructions of the United St decree of a Court of Law and /or t conformance with the rules of the M established, re-established, monume	that the corner points mention Michigan Board of Land Survey	ed in lines 3, 4 and 5 above w ors or by a Decree of a Court of	rere in 6 18 17 16 15 14 13		
NOTE: Not more than 2 corners, a on this certificate.	all in the same town and range	e, may be recorded	9		
A. Description of original monu		·	11 32 33 34 35 36		
MC #17; East Meander Co	•		13		
Utidinaliy established	d durina U.S. Survey a	conducted by William Br	urt		

No subsequent record evidence was found.

by a Sugar 12 N12°E 12 lks.

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

D.S. in 1849 and monumented with a sugar maple post witnessed

MC #17; East Meander Corner between B-9 and C-9, T52N, R33W;

This corner was considered lost and reestablished on line at the proportionate distance between the N¼ corner of section 30 and the NE corner of section 30. This corner position falls in the Sturgeon River. A witness corner was established on the section line at a distance of 82.00 feet easterly of the proportioned meander corner. The witness corner is located approximately 33 feet east of the water's edge.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

MC #17; East Meander Corner between B-9 and C-9, T52N, R33W;

The witness corner described in Part B was monumented with a 1" (I.D.) x 36" galvanized iron pipe with cap stamped as to location projecting 6" above ground.

Set 7" spike	- SW/side	13" Box Elder	N32°W	57.98
Set 7" spike	W/side	9" Elm	N05°W	81.35'
Set 7" spike	E/side	13" Box Elder	N17°E	53.04'
Set 7" spike	S/side	13" Box Elder	S83°E	51.871
6' Steel fence post w/ yellow sign			South	2.01

All of the above new bearing trees were marked with upper and lower blazes. The lower blaze was scribed "NBT". Both blazes and a band around the tree at the upper blaze were painted red.

LAND CORNER 345 OF 1990 raga County

MICHAFL

MILESKI **PROFESSIONA**

Surveyor's Michigan License No. 39091