STATE OF MICHIGAN COUNTY OF BARRY RECEIVED FOR RECORD

## BARRY COUNTY REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE

DEC 7 4 26 PM '93

For corners in	Filing Requir	ement of Act 74, Mich. P.A. 19	70 -
ror comers in			Sanday Sco
Barry	Located In:	Corner Code =##	REGISTER

ورود ومحاولهم

Barry (Gounty)	Located In:	ocated In: Corner Code ##			RECISTER OF DEEDS							
1. Public Land Survey	TINR TW T R T R T R	M-12				0	02	21.	34		-	
2. Property Controlling S	T R T R T R		Registe	er of	Deed	s Sta	mp	& Fi	le Nı	umb	er	
	d Plat			A 9								
5. Private Claims			2				4-	3	1	-2-	K	_ M
1, Daniel M. Ryan , in a find the do hereby certify that under requirement in lines 1 and 2 above were in conform current manual of survey instructions of Management or by a decree of a Court of the survey in the	its of P.A. 74, Michigan P.A. of a mance with regulations and r of the United States Departme of Law and/or that the corner p	1970, the corner points ment rules therefore as required ent of the Interior, Bureau of oints mentioned in lines 3, 4	tioned 6 in the	- /- -18- -19-	17	7	16	15		-11- -14- -14-		13-

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Court of Law; established, re-established, monumented, re-monumented, recovered, found as

Description of original monument and accessories and/or subsequent restoration:

18" White Oak, N281°W, 20 feet 18" White Oak, S14°W, 47 feet

expressed below:

Robert Carr, 1972:

호" Iron Road

0.5 feet South of East/West fence

1.5 feet West of North & South fence 20" Hickory, S2°E, 12.65 feet 12" Hickory, N70°W, 11.00 feet 26" Oak, N02°E, 19.65 feet

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found &" iron Used witnesses from Robert Carr, 1972

Survey & REMONUMENTATION

APR () 5 1994

COMMISSION

Description of monument for corner and accessories established to perpetuate locating the position of the corner. Found ½ iron rod and replaced with Barry County Remonumentation iron & cap.

60p nail in South side of 8" maple, S82°E, 20.69 feet

50p nail in West side of 30" Oak, N02°E, 19.65 feet

Nail & spotter in Northeast side of 18" Hickory, N70°W, 11.00 feet

Nail & spotter in West side of 24" Hickory, S02°E, 12.65 feet

DANIE RYA DANIEL M RYAN PROFESSIONAL SURVEYOR No. 34975 POFESSION

		13.1				7
		1//	-	-//	7//	
Signed	by .	//			150	_
0.900		-				

Surveyor's Michigan License No.

<u>September 8, 1993</u>