BARRY COUNTY REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE

STATE OF MICHIGAN COUNTY OF BARRY RECEIVED FOR RECORD

Filing Requirement of Act 74, Mich. P.A. 1970

DEC 7 3 41 PM '93

For comers in BARRY COUNTY Located In: Corner Code ## (County) 1N_R 1. Public Land Survey JOHNSTOWN TWP. 2. Property Controlling in Section S <u>:</u> T R Miscellaneous S · T

Sandy Schondelmaryer REGISTER OF DEEDS

002124

Register of Deeds Stamp & File Number

Property in Sec. Lot No. Recorded Plat 5. Private Claims ROBERT R. CARR

SEPTEMBER 1 in a field survey on . do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

- Description of original monument and accessories and/or subsequent restoration:
 - G.L.O. BLACK OAK 20" N82°W 33 LKS; WHITE OAK 10" S74°E 17 LKS. LCRC NO. 65 JAMES L. KING RLS NO. 14766 LCRC NO. 126 JAMES L. KING RLS NO. 14766 BOTH RECORDINGS CALL FOR 5/8" SQUARE IRON, SET BY PROPORTIONAL METHODS; 28" HICKORY S55°W 51.91 FT 4" STEEL POST SOUTH 36.35 FT; 2" SOLID STEELI POST NORTH 28.96 FT.
- Description of corner evidence found and/or method applied in restoring or reestablishing corner:
 - FOUND R.R. SPIKE MATCHING ABOVE WITNESSES OVER 5/8" SQUARE IRON CORNER LOCATION FITS OCCUPATION WELL, IN CENTERLINE ± OF E/W ROAD WITH FENCES RUNNING N/S ACCEPTED OCCUPATION AS BEST AVAILABLE EVIDENCE OF ORIGINAL CORNER LOCATION AND ACCEPTED CORNER AS PER PREVIOUS RECORDINGS.

Survey & **REMONUMENTATION**

APR 0 5 1994

COMMISSION

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
 - REPLACED RR SPIKE AND 5/8" SQUARE IRON WITH STANDARD BARRY COUNTY REMONSHIELD 3/4" STEEL ROD AND ALUMINUM CAP WITH CENTER PUNCH 0.3 FT BELOW SURFACE NAIL AND SPOTTER IN SE SIDE OF 30" HICKORY S66°W 51.60 FEET NAIL AND SPOTTER IN SE SIDE OF 30" ASH S47°W 43.36 FEET CENTER OF 2" SOLID STEEL FENCE POST NO3°W 29.10 FEET NAIL AND SPOTTER IN S SIDE OF 5" OAK N83°E 105.53 FEET FACE OF 4" STEEL FENCE POST SOUTH 36.30 FEET



Signed by ROBERT R.

Surveyor's Michigan License No.

Date

SEPTEMBER 8, 1993