CHEVEY & REMONUNENTATION

BARRY COUNTY REMONUMENTATION

FEB 0 3 1999

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

SECTION					
For Corners in BARRY (county)	Located in:	Corner Code#			
1. Public Land Survey CORNER COMMON TO SECTIONS 20, 21, 28 & 29 BARRY TOWNSHIP	T_1N_R_9W TR TR	E-9	- Barry Co. LCRCR	2754 Page: 1 o	f 1 2:35P
2. Property Controlling S in Section S	T R T R	Sandy Schondelmayer	Register of Deeds S	tamp & File N	<u>umber</u>
3. Miscellaneous S	T R		ABCDE	FGHIJ	KL
4. Lot No, Recorded F 5. Private Claims	Plat		2 6 5 3 4 7 8 4	9 10 11	1 12
I, Brian Reynolds, in a field survey on of P.A. 74, Michigan P.A. of 1970, the conformance with regulations and rule	e corner points mentioned es therefore as required i	in the current manual of survey	6 - 18 - 17 - 7	+	
instructions of the United States Depo a decree of a Court of Law and/or tha	artment of the Interior, Bu It the corner points menti I the Michigan Board of L	ureau of Land Management of by ioned in lines 3, 4, and 5 above _and Surveyors or by a Decree		21 - 22 - 23 	324 625
of a Court of Law; established, re-esta as expressed below. NOTE: Not more than 2 corners, all in			e. 12 31 + 32 + 13	33 34 3	5 36

A. Description of original monument and accessories and/or subsequent restoration:

1. GENERAL LAND OFFICE: SYLVESTER SIBLEY, D.S., 1826 (R9W, P. 28) W. OAK 24 S18E 47 Do. 24 N26E 48

CONSUMERS POWER COMPANY: CHASE, DEKEYSER & ALDEN, OCT 1965, "FOUND 3/" PIPE 0.65' E. OF 3" CHANNEL IRON CORNER POST IN CONC." NO WITNESSES GIVEN

*** NO OTHER HISTORICAL INFORMATION, PUBLIC OR PRIVATE, AVAILABLE FOR THIS CORNER ***

B. Description of comer evidence found and/or method applied in restoring or reestablishing comer: FOUND 3/" PIPE AS RECITED IN ITEM #2 ABOVE. MEASUREMENTS TO CORRESPONDING CORNERS IN SECTION 21 INCLUDING OCCUPATION TIES CONFORM WELL WITH FOUND PIPE. ACCEPTED FOUND PIPE AS BEST AVAILABLE EVIDENCE OF CORNER POSITION. WERE UNABLE TO REMOVE FOUND PIPE. LEFT FOUND PIPE IN PLACE AND SET STANDARD BARRY COUNTY REMONUMENTATION ALUMINUM CAP ON TOP.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner. SET STANDARD BARRY COUNTY REMONUMENTATION MONUMENT (3/4" X 36" IRON) WITH ALUMINUM CAP. FOUND 20d NAIL W/PLASTIC TAG IN THE NORTHEAST SIDE OF A 20" HICKORY S46°E 6,35" FOUND 20d NAIL W/PLASTIC TAG IN THE NORTHEAST SIDE OF A 32" OAK N86°W 4.88' FOUND "PK" IN THE SOUTH SIDE OF A 32" OAK N86°W 4.78' FOUND 20d NAIL W/PLASTIC TAG IN THE WEST SIDE OF A 22" OAK N30°E 12.80' FOUND 20d NAIL W/PLASTIC TAG IN THE EAST SIDE OF A 300AK N03°E 21.59' SOUTH FACE OF IRON FENCE CORNER POST IN CONCRETE N79°W 0.65' CORNER LIES 0.5'± EAST OF NORTH-SOUTH FENCE IN LINE WITH EAST-WEST TREE/FENCE LINE

> ACT 345 BARRY COUNTY REMONUMENTATION APPROVED BY PEER REVIEW AT A MEETING HELD ON

> 4 Sept 98 COUNTY SURVEYOR RRIAN REYNOLDS



man Maria Maria	Date 1 EC 15, 1998
Signed by	FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971
Surveyor's Michigan License No 31602	PENNIA PROVIDE STATE REVISED LANUARY 1983 REVISED OCTOBER 1995