

1993

COMMINISSION

expressed below:

on this certificate.

STATE OF MICHIGAN COUNTY OF BARRY RECEIVED FOR RECOIL

BARRY COUNTY REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE

3 07 PM '93

Filing Requirement o	f Act 74,	Mich.	P.A. 1970
----------------------	-----------	-------	-----------

For corners in		,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	Sandy Schondelmaryer
BARRY (County)	Located In: MAPLE GROVE	Corner Code ##	REGISTER OF DEEDS
Public Land Survey	T <u>2N</u> R <u>TW</u> T R T R T R	E-5	002060
2. Property Controlling in Section			
3. Miscellaneous	S T R		Register of Deeds Stamp & File Number
Property in Sec.	S T R	<u></u>	register of beeds stamp at the ranner
4. Lot No	_ , Recorded Plat		A B C D F F G H I J K 1
5. Private Claims			2 6 5 4 3 2 1
		,	3 1 1 1 1 1 1 1
DARFET B. CARD	DCCCMOCO :	7 00	4 7 8 9 10 11 12
	, in a field survey on _DECEMBER ?		
in lines 1 and 2 above we current manual of survey it	er requirements of P.A. 74, Michigan P.A. of ere in conformance with regulations and instructions of the United States Department of a Court of Law and/or that the corner	rules therefore as required in ment of the Interior, Bureau of	in the 17 16 15 14 13 13 Land 7

A. Description of original monument and accessories and/or subsequent restoration: SETH PRATT, APRIL 1890; STAKE, SYCAMORE 8" N 38-3/4 W, 21-1/2 LINKS.

NOTE: Not more than 4 corners, all in the same town and range, may be recorded

above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as 10 11 12 13

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

FOUND 3/4" PIPE 3 FT SOUTH OF CENTERLINE OF EAST AND WEST ROAD AND 6 FT WEST OF CENTERLINE OF ROAD TO SOUTH. ACCEPTED AS PERPETUATION OF ABOVE.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

PLACED STANDARD BARRY CO REMON 3/4" ROD AND ALUM CAP WITH CENTER PUNCH AND RECESSED IN BITUMINOUS SURFACE.

3' SOUTH OF CENTERLINE OF EAST/WEST ROAD

3' SOUTH OF CENTERLINE OF EASI/WEST KUAD
6' WEST OF CENTERLINE OF ROAD TO SOUTH
NAIL AND REMON SPOTTER IN EASTERLY
SIDE OF UTILITY POLE N12°W, 36.85 FT.
NAIL AND REMON SPOTTER IN SOUTHWESTERLY
SIDE OF FENCE CORNER POST
S48°E, 51.65 FT.
IN LINE WITH FENCE LINE TO NORTH
CENTER OF TELEPHONE RISER N50°E, 50.65 FT.

Date Signed by . ROBERT R. CARR Surveyor's Michigan License No.

20704

SURVEYOR No. 20704 PROFESSION ESSI-JULY 13, 1993

OF MICHIG

ROBERT R CARR PROFESSIONAL