SURVEY & REMONUMENTATION

NOV 04 1996

Lot No. . 5. Private Claims

expressed below

STATE OF MICHIGAN COUNTY OF BARRY RECEIV! AFT

COMMISSION

LAND CORNER RECORDATION CERTIFICATE OCT 17 3 16 PM 15 Filing Requirement of Act 74, Mich. P.A. 1970

Fo	r corners in			Sanday Swambline yer
_	BARRY (County)	Located In:	Corner Code ##	REGISTER OF DEEDS
1.	MAPLE GROVE Public Land Survey	TOWNSHIP	F-2	002413
	,	T R T R		005410
		T R		
2.	Property Controlling in Section	S T R S T R		
3.	Miscellaneous Property in Sec.	S T R S T R		Register of Deeds Stamp & File Num

ber

DAVID L. CLIFFORD in a field survey on SEPTEMBER 24 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

- 10
- A. Description of original monument and accessories and/or subsequent restoration:
- 1. POST NOT SET IN ORIGINAL GOVERNMENT SURVEY

____ , Recorded Plat __

- 2. A.C. WILLSON, COUNTY SURVEYOR SET STONE & PLOW POINT FOR CORNER FROM A PREVIOUS SURVEY IN A SURVEY RECORDED IN LIBER 2 PAGE 189 IN NOV. 1867.
- 3. D. FLUKE LS #18988 RECORDED CORNER AS $\frac{1}{2}$ " BAR & CAP BETWEEN FOUND STONE & PLOW POINT IN ACT 74 RECORDATION CERTIFICATE #380 IN JUNE 1987 WITH THE FOLLOWING WITNESSES: N57E 68.67' POPLAR 10"; WEST 63.27' CORNER POST (MODEL A FRAME); N57W 108.00' END 3' CULVERT; WEST 84.70 EDGE OF BIT. ROAD
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:


SEARCHED AT APPARENT LOCATION OF CORNER AND FOUND &" BAR & CAP #18988 BETWEEN STONE AND PLOW POINT IN EAST-WEST FENCE LINE. TRAVERSE OF SECTION 4 T2N R7W SHOWS STONE & PLOW POINT TO BE 0.75' SOUTH AND 3.1' WEST OF THE INTERSECTION OF $\frac{1}{4}$ LINES. ACCEPTED STONE AND PLOW POINT AS CORNER AS ESTABLISHED BY A.C. WILLSON, COUNTY SURVEYOR AND PERPETUATED BY D. FLUKE PS #18988. SET STANDARD BARRY COUNTY MONUMENT BETWEEN STONE AND PLOW POINT.

> **ACT 345 BARRY COUNTY REMONUMENTATION** APPROVED BY PEER REVIEW AT A MEETING HELD ON **BRIAN REYNOLDS** COUNTY SURVEYOR

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

F-2 T2N R7W

3/4" DIAMETER STEEL BAR AND ALUMINUM CAP IMPRINTED "BARRY COUNTY REMOMUMENTATION PS 31602 28409" BETWEEN STONE AND PLOW POINT. NAIL & TAG #28409 IN SOUTH SIDE 13" POPLAR, MAG. AZ. 61°, 68.67' FACE ANCHOR POST (MODEL A FRAME), MAG. AZ. 273°, 63.27' PUNCH MARK IN EAST END CMP, MAG. AZ. 306°, 108.05 EAST EDGE BITUMINOUS ROAD, MAG. AZ. 273°, 84.70' NAIL & TAG #28409 IN EAST SIDE 6" CHERRY, MAG. AZ. 185°, 30.00'



			A STANSANT PROPERTY.
		OCTOBER 09, 1996	
Signed by	25837	Date	
Surveyor's Michigan License No	23037	COON ADDROUGH BY SECURIOUS CTATE	POARD OF LAND SUBVEYORS JAN 28 197