BARRY COUNTY REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE

SURVEY & MOTATION

BEN Filing Requirement of Act 74, Mich. P.A. 1970 APR 0 4 2000 For Corners in Located In: Corner Code # BARRY SECTION (county) 1. Public Land Survey 2N R 7W % CORNER COMMON TO **SECTIONS 24 & 25 MAPLE GROVE TOWNSHIP** Page: 1 of 1 2. Property Controlling S in Section Register of Deeds Stamp & File Number 3. Miscellaneous B CD EFGH 4. Lot No , Recorded Plat 5. Private Claims 12 I, Brian Reynolds, in a field survey on 09 JULY, 1999 do hereby certify that under requirements 5 of P.A. 74, Michigan P.A. of 1970, the comer points mentioned in lines 1 and 2 above were in 8 18 18 13 conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by 8 20 a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4, and 5 above 21 22 23 24 9 were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found 10 30 28 26 25 as expressed below 11 NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate. 12 30 33 A. Description of original monument and accessories and/or subsequent restoration:
GENERAL LAND OFFICE: MUSGROVE EVANS, D.S., 1826 (R7W, P.58) CHERRY 12 S49W 22 Be. 14 N40E 20 COUNTY SURVEYOR RECORDS: FRANK BOWEN, 18 JANUARY, 1876 (L.1, P.136) "FOUND STONE FOR CORNER" NO WITNESSES GIVEN *** NO OTHER HISTORICAL INFORMATION, PUBLIC OR PRIVATE, AVAILABLE FOR THIS CORNER *** B. Description of comer evidence found and/or method applied in restoring or reestablishing corner: FOUND A 1/2" X 6" RAILROAD SPIKE 1' BELOW ROAD GRADE. FURTHER EXCAVATION TO A DEPTH OF 2.5' REVEALED THREE STONES. THE THREE STONES FORM A CRUDE TRIANGLE BEING 0.9' APART. FURTHER EXCAVATION REVEALED NOTHING. TRAVERSED ALL OF SECTION 25, TYING OCCUPATION. HELD POSITION OF LARGEST STONE, N45°W± 0.9' FROM FOUND SPIKE, FOR CORNER.

SET STANDARD BARRY COUNTY REMONUMENTATION MONUMENT AND INSTALLED MONUMENT BOX.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: SET STANDARD BARRY COUNTY REMONUMENTATION MONUMENT (3/4" X 36" IRON) WITH ALUMINUM CAP. CHISELED DRILL HOLE IN THE TOP CENTER OF A CONCRETE FILLED PIPE CORNER POST N30°E 40.26' SET 20d NAIL WIPLASTIC TAG IN THE SOUTHWEST SIDE OF A 10" WALNUT N07°E 82.28' SET 20d NAIL W/PLASTIC TAG IN THE NORTH SIDE OF A UTILITY POLE \$79°W 171.90' SET 20d NAIL WIPLASTIC TAG IN THE SOUTHWEST SIDE OF A 12" POPLAR S64°W 173.78' SET 20d NAIL W/PLASTIC TAG IN THE SOUTHWEST SIDE OF A UTILITY POLE \$53°W 69.66'

> ACT 345 BARRY COUNTY REMONUMENTATION APPROVED BY PEER REVIEW AT A MEETING HELD ON

12 July,99 BRIAN REYNOLDS

COUNTY SURVEYOP

#10 H BRIAN REYNOLDS AND SURVEYOR 31602 CARDS

Signed by	(Son)		
Surveyor's Michig	an License	No 3160	2

Date