APR 0 4 2000

SECTION

## Barry County Remonumentation Program LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in Orangeville Township Quarter Corner 11, 12

Barry (County)	Located in:	Corner Code #	
1. Public Land Survey	T2N R10W T R T R T R	<u>K4</u>	2760 Page: 1 of 1 01/27/1999 03:56P
<ol> <li>Property Controlling in Section</li> <li>Miscellaneous Property in Sec.</li> </ol>	S T R S T R S T R S T R	Sandy Schondelmaye	er - Barry Co. LCRCR  Register of Deeds Stamp & File Number
4.Lot No, Record 5.Private Claims	ded Plat		A B C D E F G H I J K L ! 2   1   1   1   1   1   1   1   1   1
P.A. 74, Michigan P.A. of 19 conformance with regulations instructions of the United Sta decree of a Court of Law and/	770, the corner points mention and rules therefore as requir tes Department of the Interior, or that the corner points mention	preby state that under requirements of the in lines 1 and 2 above were it red in the current manual of survey Bureau of Land Management or by a oned in lines 3, 4, and 5 above were it urveyors or by a Decree of a Court o	n 5
Law; established, re-establishe	ed, monumented, recovered, foun corners, all in the same town	nd as expressed below:  n and range, may be recorded	9 10 30 29 28 27 26 25 11 1 2 31 32 33 34 35 36
A. Description of original n	nonument and accessories ar	nd/or subsequent restoration:	13

K4, Post set by US Deputy Surveyor S Sibley in January 1827, witnessed to a White Oak 9, N1-1/2°E, 27 links and a White Oak 14, S33°E, 22 links. In April 1867, County Surveyor AC Willson set a stake and stone by US trees (Liber 2, page 144). In Liber 2, page 146, Willson notes that he set post by bearings. Field notes by Cobb record that he searched for this corner October 15, 1889 and failed to find it. Cobb stated that he measured the mile and set a stake 6 feet east of a Black Oak 8. Cobb stated that he was later told that a crock was buried in place of the original stake. This same note by Cobb also appears in the record for the east quarter corner of Section 12 (M4). A corner record card from the Office of County Surveyor B Reynolds dated February '85 record finding a 2 ½" axle 3 feet deep and raising it with a ½" iron. Witnesses on the card are a quad 12" Oak, N50°W, 52.10; a 12" oak, S35°W, 84.32; a 12" Oak, East, 29.64.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

K4, Found ½" over 2 ½" axie and all witness trees from the card. Accepted the axle as the best available evidence of the position of the original corner.

ACT 345 BARRY COUNTY REMONUMENTATION
APPROVED BY PEER REVIEW AT A MEETING HELD ON
APRIL 14, 1997

RDIAN REVIEW DS COUNTY SURVEYOP

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

K4, Left axle in place 3 feet deep. Replaced ½" rebar with 24" rod with Barry County Remonumentation Program Cap. Rod and cap are foot deep. Witnessed:

Set nail with Barry County tag in east side quad 12" Oak, N50°W, 52.22 Set nail with Barry County tag in east side 12" Walnut, S35°W, 84.32 Set nail with Barry County tag 5' high in 12" Oak, East, 29.61 Set nail with Barry County tag in E side pole, S10°W, 106.28

Three feet south of centerline Mullen Road west

Signed by C. S. Locu
Surveyor's Michigan License No. 26453

Date December 30, 1998

GARY C.
BILOW
PROFESSIONAL
SURVEYOR
No.
28453