REMONUMENTA

## BARRY COUNTY REMONUMENTATION RECEIVED FOR RECONST

STATE OF HICHIGAN COUNTY OF BARRY

AUG 2 2 1995

COMMISSION

For corners in

in Section

Miscellaneous

Property in Sec.

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

8 34 M

ا بدو حس	• •
marker S-O 10	
Sandy Schondelm	محبنره
1	I

BARRY (County)	Located In:	Corner Code ##	RECISTER OF DEEDS

1. Public Land Survey CENTER OF SECTION 7 RUTLAND TOWNSHIP 2. Property Controlling

\_ T \_

Т

Register of Deeds Stamp & File Number

\_ , Recorded Plat \_ 4. Lot No. 5. Private Claims \_

\_ R

R

20 OCTOBER BRIAN REYNOLDS in a field survey on 19 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

- Description of original monument and accessories and/or subsequent restoration:
- CORNER NOT SET BY GENERAL LAND OFFICE
- COUNTY SURVEYOR RECORDS: A.N. BATEMAN, MAR 30, 1902 (L.3,P.62), "STAKE SET BY FORMER SURVEYOR"
- NO OTHER RECORDED HISTORICAL INFORMATION AVAILABLE FOR THIS CORNER 3
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

FOUND OLD DECAYING FENCES RUNNING EAST-WEST, AND SOUTH. EXCAVATED AT INTERSECTION OF FENCES AND AT 18" BELOW SURFACE, FOUND A CIRCLE OF SMALL STONES MIXED WITH CHARCOAL. UPON FURTHER EXCAVATION FOUND A VERY OLD DECAYING WOOD STAKE (APPROXIMATELY 4" X 20") (OBVIOUSLY NOT A FENCE POST), INSIDE THE CIRCLE OF STONES, WITH A VERTICAL COLUMN OF CHARCOAL ALONG THE WEST EDGE.

REPLACED DECAYING WOOD STAKE WITH STANDARD BARRY COUNTY REMONUMENTATION MONUMENT

ACT 345 BARRY COUNTY REMONUMENTATION APPROVED BY PEER REVIEW AT A MEETING HELD ON

1 NOV. 1994 **BRIAN REYNOLDS** 

COUNTY SURVEYOR

OF MICHIO BRIAN REYNOLDS LAND SURVEYOR NO. 31602 CLAND SV

C. Description of monument for corner and accessories established to perpetuate locating the position of the

SET STANDARD BARRY COUNTY REMONUMENTATION MONUMENT (3/4"X36"W/ALUMINUM CAP) SET 40d NAIL W/PLASTIC CAP IN THE WEST SIDE, NORTHWEST TRUNK OF A 12" MULTI OAK S15°W 10.94" SET 40d NAIL W/PLASTIC CAP IN THE NORTHEAST SIDE OF A 12" OAK S33°E 31.83' SET 40d NAIL W/PLASTIC CAP IN THE NORTHWEST SIDE OF A 14" OAK N55°E 11.60' SET 40d NAIL W/PLASTIC CAP IN THE EAST SIDE OF A 12" OAK N30°W 5.01 SET 40d NAIL W/PLASTIC CAP IN THE SOUTH SIDE, SOUTH TRUNK OF A 20" TWIN OAK \$70°E 47.94" CORNER LIES 1'+/- EAST OF DECAYED FENCE RUNNING SOUTH

CORNER IS IN LINE WITH DECAYED FENCE RUNNING EAST-WEST

4NUARY 24, 1995 Date Signed by Surveyor's Michigan License No. .