

JUL 2 4 1997

BARRY COUNTY REMONUMENTATION

COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

02495

				OOMIG	•
For Corners in BARRY (county)	Located In:	Corner Code #	 	STATE OF MICHIO BARRY COUNTY RECORDED	
1. Public Land Survey TOWNSHIP CORNER COMMON TO TOWNSHIPS 4 & 5NORTH RANGES 7 & 8 WEST	4N R 8W T 4N R 7W T 5N R 7W T 5N R 8W	M-1 BARRY A-1 Baley A-13 Iohia M-13 Ionia	~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~	17 JUN 97 12:18 SANDY SCHONDELI REGISTER OF DE	KAYER
2. Property Controlling S_ in Section S_	TR	(Register	of Deeds Stamp &	File Number
3. Miscellaneous S_ Property in Sec. S_	TR TR	 	75	TSNT	
4. Lot No, Recorde 5. Private Claims	ed Plat		B C D	A-13	J K L N
I, Brian Reynolds, in a field survey of P.A. 74, Michigan P.A. of 1970, the conformance with regulations and resinstructions of the United States Dear a decree of a Court of Law and/or the were in conformance with the rules of a Court of Law; established, reestables as expressed below. NOTE: Not more than 2 corners, on this certificate.	he corner points mentioned in li ules therefore as required in the partment of the Interior, Bureau nat the corner points mentioned of the Michigan Board of Land S stablished, monumented, re-mo	nes 1 and 2 above were in current manual of survey of Land Management or by in lines 3, 4, and 5 above Surveyors or by a Decree numented, recovered, found	4 7 8 5 18 17 7 8 19 20	28 27	2
•			-		

- A. Description of original monument and accessories and/or subsequent restoration:
- 1. GENERAL LAND OFFICE: SYLVESTER SIBLEY, D.S., 1826 (R8W,P.138) BEECH 11 N70E 19 SUGAR 8 N68W 13 1/2
- 2. NO REFERENCE FOUND IN THE BARRY COUNTY SURVEYOR RECORDS.
- 3. BARRY COUNTY ROAD COMMISSION: NO NAME OR DATE "IRON AND STONE" U.P. N45W 42.3" U.P. GUY S45W 36.3' 30" ELM S50E 46.3"
- 4. IONIA COUNTY ROAD COMMISSION, 1958 3/4" IRON PIN P. POLE N45°W 42.74' GUY POLE N44°E 36.50' 30" ELM \$56°E 47.40" ROAD SIGN S44°W 36.45'

*** NO OTHER RECORDED HISTORICAL INFORMATION AVAILABLE FOR THIS CORNER ***

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: FOUND A 6" BOAT SPIKE FLUSH WITH PAVEMENT. EXCAVATED AND FOUND A 12" BOAT SPIKE DIRECTLY UNDER 6" BOAT SPIKE. NO WITNESSES RECITED IN PART "A" COULD BE FOUND. ACCEPTED FOUND BOAT SPIKES AS

REPLACED FOUND BOAT SPIKES WITH STANDARD BARRY COUNTY REMONUMENTATION MONUMENT.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: SET STANDARD BARRY COUNTY REMONUMENTATION MONUMENT (3/4" X 36" IRON) WITH ALUMINUM CAP. FOUND NAIL W/CAP #28424 IN THE NORTHWEST SIDE OF A UTILITY POLE \$47°W 41.69' FOUND NAIL W/CAP #28424 IN THE SOUTH SIDE OF A 22" MAPLE N79°W 165.07 FOUND NAIL W/CAP #28424 IN THE SOUTH SIDE OF A 12" WALNUT N79°E 126.66' FOUND NAIL W/CAP #28424 IN THE NORTH SIDE OF A UTILITY POLE S84°E 209.02' SET 40d NAIL W/PLASTIC TAG IN THE SOUTH SIDE OF A GUY POLE N85°E 209.87' MICH CORNER IS ON CENTERLINE OF NORTH-SOUTH-EAST-WEST ROADS

APPROVED BY PEER REVIE	ITY REMONUMENTATION W AT A MEETING HELD ON	
5-3-94		
BRIAN REYNOLDS	COUNTY SURVEYOR	
igned by		

31602

Surveyor's Michigan License No

BEST AVAILABLE EVIDENCE OF CORNER POSITION.

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971

BRIAN REYNOLDS LAND SURVEYOR NO. 31602