SURVEY & REMONUMENTATION

FFR 1 7 1998

BARRY COUNTY REMONUMENTATION

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

002521 STATE OF MICHIGAN Corner Code # Located In: For Corners in BARRY CHUNTY BARRY RECUEDED (county) 31 JUL 97 9:05 A.M. T_4N R_9W G-12 1. Public Land Survey _ R_ 1/4 CORNER COMMON TO SAMBY SCHOODELMAYER SECTIONS 33 & 34 ACGISTER OF DEEDS IRVING TOWNSHIP 2. Property Controlling S____ T___ R__ in Section S___ T___ R__ Register of Deeds Stamp & File Number ___ T____R_ 3. Miscellaneous Property in Sec. _, Recorded Plat 4. Lot No_ A B C D E F G H I J K L M 5. Private Claims 2 6 5 4 3 2 1 1 I, Brian Reynolds, in a field survey on 10 DECEMBER, 1996 do hereby certify that under requirements 10 | 11 | of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey 15 14 18 | 17 | 16 instructions of the United States Department of the Interior, Bureau of Land Management or by 6 a decree of a Court of Law and/or that the comer points mentioned in lines 3, 4, and 5 above ___1 8 | 19 | 20 | 21 | 22 | 23 | 24 | were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found 9 | | | | 1 27 | 26 | 25 | 10 | 30 | 29 | 28 | as expressed below. 1 1 ______ 11 | | | 34 | 35 | 36 | 12 | 31 | 32 | 33 NOTE: Not more than 2 corners, all in the same town and range, may be recorded 13 | | | | | | on this certificate.

- A. Description of original monument and accessories and/or subsequent restoration:
- 1. GENERAL LAND OFFICE DEPUTY SURVEYOR SYLVESTER SIBLEY, 1830, "A W. OAK 7 S64W 21

6 N52E 9 Do

- 2. NO MENTION OF THIS CORNER COULD BE FOUND IN THE COUNTY SURVEYOR RECORDS.
- 3. ACT 132 SURVEY BY ROBERT E. VAN LAAR, P.S. 21589, JULY 16, 1986 (L.1,P.843) "T IRON" NAIL IN SE SDE 14" OAK NE 10.20' NAIL IN N SDE 6" W. CHERRY ESE 18.42' NAIL IN W SDE 5" W. CHERRY NORTH 19.60' OLD WOOD FENCE CORNER POST 0.5' N; 0.4' EAST OF IRON.
- ACT 132 SURVEY BY DOUGLAS W. BONNEMA,P.S. #12579, SEPT. 25,1987(L.1,P.862) RECITE SAME WITNESSES AS

IN #3 ABOVE.	· ·	
B. Description of corner evidence found and/or method a	applied in restoring or reestablishing corner:	
FOUND "T" IRON AND ALL WITNESS TREES FI AVAILABLE EVIDENCE OF CORNER POSITION REMONUMENTATION IRON AND CAP.	ROM ITEMS 3 AND 4 ABOVE. ACCEPTED "T" . REPLACED "T" IRON WITH STANDARD BA	RON AS BEST
C. Description of monument for corner and accessories SET STANDARD BARRY COUNTY REMONUME SET 20d NAIL W/REMON TAG IN THE SW ROO' SET 20d NAIL W/REMON TAG IN THE SE SIDE SET 20d NAIL W/REMON TAG IN THE S SIDE O SET 20d NAIL W/REMON TAG IN THE E SIDE O 1/2' +/- SW OF CORNER FENCE POST	NTATION MONUMENT (3/4" X 36" IRON) WITH T OF 16" OAK N30°E 9.25' OF 10" CHERRY N45°E 19.57' OF 12" CHERRY S88°E 17.53'	BRIAN REYNOLDS LAND SURVEYOR NO. 31602
Signed by 24602	Date JVLY 30, 1	BOARD OF LAND SURVEYORS, JAN. 28, 1971