• -								
MAR 3 1 19	ga .		UED DECORDATION	05071710477			ഫെ	٣0
	15.1	— · · · · · ·	NER RECORDATION			LIBER	ะ ุบบป	PAGE 59
For corners in	.J. 4. 1 /		irement of Act 74, N					
For corners in		BAY COUNTY	REMONUMENTATION	PROJECT - 1	993	B _ 1		
BAY		Located In:	Corner Code ≠	<i>‡</i>				
(County)						\$ 25g	27	~===
Public Land Survey		T 13N R 6E	K-9			多量差	` <u>'</u>	in in
T. Funic Land Survey		T R				358	·	CORDE
•		T R		1		¥ 7	- 5	30
		T R				- 3₩ <i>\$</i>		0.0
2. Property Controlling	S	τ R		l		GA S		
in Section		T R				Z 3	ু কু	
3. Miscellaneous				í	ister of	Doods Sta	ımp & File	Number
Property in Sec.						Deeds Oil	and or ne	Tunber
							-	
4. Lot No,	Recorded	Plat			А В	C D E	F G H	IJKLN
5. Private Claims						TIT		
					2 6-	5	-4-1-3	1-1-1-
		^			3	- - -	++	
		/ ₁).			4 - 7-	8 	- 910	1/1-12-
I. Duane F. Ledy , in a field survey on VECEMBER 27, 1993.					5	- - - 	 	
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the					618	17-	-1615	14 13
current manual of survey inst		_			7		+	1-1-1-
Management or by a decree o			•	•	8 — 19-		-2122	23 24
above were in conformance we Court of Law; established,					9			
expressed below:	re-estatini	sned, mondinenced, i	e-monumented, recovere	ed, louiso as	1030		-2827	26 25
NOTE: Not more than 4	corners a	all in the same town	and range may be re-	corded	11			
NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.					12 31		33	35 36
		•			13	J j		
A. Description of original	l monume	nt and accessories a	and/or subsequent rest	oration:				•

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 3/8" rod; L.C.R.C. in L001 P195 recorded in May 1972 indicate a 3/8" rod was found; C.P.Co. survey in August, 1972 found 3/8" rod with same witnesses as in L.C.R.C. Survey dated 7-31-73 and recorded in L716 P608 used same corner. Corner accepted by Bay County Peer Review Group, ratified on October 28, 1993.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Replaced 3/8 rod with 5/8 rod and Bay County brass cap in monument box.

s 45° W -45.10' Nail & Tag in Power Pole

Post set at 80.00 chains North of K-11 (1834)

N 45° W N 10° E

-49.33' Nail & Tag in Power Pole -24.75' 1/2" X 18" rod W/21575 Cap -15.35' 1/2" X 18" rod w/21575 Cap

S 45° E



Signed by

Surveyor's Michigan License No. ____21575

Date