LIBER 003 PAGE 47

BAY COUNTY REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For	corners	in	
1 01	COHICIS	111	

	DAI	Located In: Sec. 19	Corner Code =##
	(County)		0511101 0000 77
1.	Public Land Survey	T 14 R 3	(A#)
		T <u>14</u> R <u>3</u>	A=8
		T R	
		T R	
2.	Property Controlling	S R	
	in Section	S T R	<u>.</u>

15:19	7	72
REGISTER OF DEEDS	2 25 PN '94	RECORDED
4,	٠	

Register of Deeds Stamp & File Number

	i		
4.	Lot No.	Recorded F	'lat

Private Claims

3. Miscellaneous


Property in Sec.

1, Donald R. Burgin, in a field survey on October 30, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, tound as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Description of original monument and accessories and/or subsequent restoration:

A-7 L.C.R.C. L.2 P.599 A-8 L.C.R.C. L.2 P.295



SURVEY & REMONUMENTATION

MAR 3 1 1994

COMMISSION

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
 - Found 3/8" rod in Mon. Box over 3/4" pipe 1.5 ft. deep Removed & replaced with 5/8" rebar and Brass Cap
 - A-8 Found 3/8" rod in Mon. Box Removed & replaced with 5/8" rebar and Brass Cap



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

North 11.75 ft. to 1" pin in mon. box NE cor. Sec. 24, T14N, R2E (Midland County)

N 13°E 63.47 ft. to spike in 18" Poplar tree

S 78°W 95.52 ft. to 1/2" rod in headwall

N 75°W 147.3 ft. to chiseled "X" in SE corner of bridge pier - 0.7' above ground, South face

์ 15°พ 149.1 ft. to nail with Remon. tag

in SW face of utility pole N 51°E 55.97 ft. to nail in NW face of utility pole

S 40°E 62.22 ft. to top centerline of fire hydrant

S 50°W 64.73 ft. to M.D.O.T. tag with double head nail in NW face of utility pole

S 28°E 53.5 ft. to M.D.O.T. tag with double head nail in NW face of utility pole

AR. Pun. Signed by

Date <u>12/23/93</u>

Surveyor's Michigan License No. _

29240

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975

REVISED JAN., 1983