## REMON. COR. G-5, WILLIAMS TWP. LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

RECORDED

SECTION

		•
For comers in	e	Corner Code #
(County)	Located in:	
1. Public Land Survey	T 14N R 3E	<u>G-5</u>
,,,	TR_	
	TR s TR	
Property Controlling     in Section	S T T R	
3. Miscellaneous	S — Ţ—B—	
Property in Sec.	S ''\	

1999 DEC 28 P 1: 02

Garken Torle Da Fecus REGISTER OF DEEDS BAY COUNTY, MICHIGAN

Register of Deeds Stamp & File Number

, Recorded Plat 4. Lot No. 5. Private Claims

I, <u>JERRY L. JONES</u>, in a field survey on <u>June 16</u>, 1999, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned on lines 1 and 2 above. Ware in conformance with require lines 1 and 2 above were in conformance with regulations and rules therefore as required ines I and Z above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; re-established, manumented recovered found as expressed below. monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 2 comers, all in the same town and range, may be recorded on this certificate.

ABCDE	F G	н 1	JK	ſ W
2 6 + 5 +	4	3	- 2 +	1 1
3	-+ <del> </del>	- <del> </del>   10		12
4 7 T 8 T 5 + + + + + +	9 1		-1-	- 13 -
6 18 + 17 +	16	15	14 7	
8 19 + 20 +	21	- 22	23	24
9 29 29	- 28 -	- 27-	- 26 -	25
11 - 1 - 1 - 1 - 31 - 32 -	<del>- 1</del>	- 34 -	- 35 -	36 -
12 7 72		1	<u></u>	

- A. Description of original monument and accessories and/or subsequent restoration:
- Corner common to Sections 9, 10, 15 and 16 G-5

Survey by Gio, 1031, set post Survey by Edmands Engineering, 1969, 1972, 1973, 1979, 1983, 1985, found ½" pipe Survey by J. Schafer, 1974, 1975, 1976, found ½" pipe Survey by D. Burgin, 1984, found ¾" pipe; 1987, 1991, found ½" pipe Survey by Wade-Trim, 1989, 1994, 1995, found ½" pipe

Survey by J. Jones, 1998, found 1/2" pipe LCRC by L. McGinnis, 1974, found 1/2' pipe

LCRC by J. Schafer, 1974, found 1/2" pipe

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- Corner common to Sections 9, 10, 15 and 16

Found 1/2: pipe per surveys by Edmands Engineering, J. Schafer, D. Burgin, Wade-Trim, J. Jones and LCRC's by J. Schafer and L. McGinnis

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- Corner common to Sections 9, 10, 15 and 16

Found 1/2" pipe, replaced pipe with 5/8" rod and brass cap stamped Bay County Remonumentation PS 19838 in monument box and i accepted as the best available evidence of the position of the accepted corner. OF MICHIQ

S 50 Deg W, 48.78', pk nail in power pole (Rec. as 49.4')
N 65 Deg W, 80.15', nail in power pole (Rec. as 80.15')
S 45 Deg E, 53.95', pk nail in power pole (Rec. as 54.03')
S 45 Deg E, 54.05', nail & disc in power pole (Rec. as 53.98')
N 60 Deg E, 47.17', pk nail in power pole (Rec. as 47.40')
N 65 Deg W, 80.20', nail and survey disc in power pole (Rec. as 80.20')

Signed by Surveyor's Minigan License No. 199

Date 12/09/39

Form approved by Michigan State Board of Land Surveyors, Jan.

Revised May 14, 1971 Revised Jan., 1983

**IERRY L** JONES ROFESSIONA SURVEYOR No. 19838

OFESSION

004

APPROVED LAND CORNER PA 345 OF 1990 - Bay County Date 9. 09. 99

Michael MacDonald P.S. County Nepresentative