SURVEY & REMONUMENTATION

APR 23 1998

REMON COR. J-7, WILLIAMS TWP LAND CORNER RECORDATION CERTIFICATE Filing Requirement of AAATA Mich. D.A. 4070

For corners i	SECTION	Filing Requi	rement of Act 74, Micl	h. P.A. 1970	
Bay (Cour	nty)	Located in:	Corner Code #	<u> </u>	r e
1. Public Lar	nd Survey	T <u>14N</u> R <u>3E</u> T R T R	J-7	AY COUNTY.	
 Property 0 in Section Miscellane Property in 	ous	T R R S T R		-	DED NY '97
 Lot No. Private Cla 	, Recorded Plaims	at		ABCDI	EFGHIJKL
that under requilines 1 and 2 about in the current imminterior, Bureau of corner points month of the Michigan immonumented, respectively. NOTE: Not record. A. Description	rements of P.A. 74, Miclove were in conformant anual of survey instructed Land Management of Land Management of entioned in lines 3, 4 a Board of Land Surveyor e-monumented, recover more than 2 corner ded on this certification.	nent and accessories ar	r points mentioned on therefore as required Department of the Law and/or that the nance with the rules of Law; re-established, w:		-4 -3 -2 -1 -1 -1 -1 -1 -1 -1 -1 -1 -1 -1 -1 -1
	nment survey, 1830's, s by Hunter-Whittier, 193	⊒t post 78, found 3/8" rod, L-841, P-1	56, and P-155		IERRY L. JONES FROFESSIONAL SURVEYOR No.
WITNESS NO	TE: Witnesses from presented to μ	n above surveys and LC Deer review committee a	CRC's are available in d and is on file at the Reg	Ossier file: which was	No. 19838 OFESSION
B. Description	n of corner evidenc	e found and/or method	applied in restoring or	reestablishing corner:	A STATE OF THE STA
J-7 1/4 cor	rner common to Section	ns 14 and 23			
Found	"T" bar per survey by H	unter-Whitter (bent 3/8" rod t	under "T" iron)		
C. Description	n of monument for	corner and accessories	established to perpetu	ate locating the position	n of the corner:
J-7 1/4 cor	ner common to Section	is 14 and 23			
Found and is a	"T" bar per survey by H accepted as the best av	unter-Whittier, replaced rod v allable evidence of the positi	rith 5/8" rod and brass cap on of the accepted corner.	stamped, Bay County Remor	numentation PS 19838 in mon I
N 70 De N 2 Deg N 22 De S 70 De	eg W, 82.82', SE corner eg W, 75.40, SE corner g E, 33.35', pk nail in po eg W, 26.56', centerline eg W, 76.01', pk nail in p 32.7', broken plat mon	concrete drive wer pole top hydrant		APPROVED LAND (P.A. 345 OF 1990 - Date 37 Tone Michael MacDonald County Representat	Bay County S.Z P.S.
Signed by	Jen	ud.Oou	Da Da	te ///05/	97
Surveyor's Mic	chigan License No.	19838		ov Michigan State Board of L	and Suprevore Ian 29, 1071

Revised May 14, 1971 Revised Jan., 1983