SURVEY & REMONUMENTATION

APR 2 3 1998

REMON COR. M-9, WILLIAMS TWP LAND CORNER RECORDATION CERTIFICATE

For some 35 three areas		ement of Act 74, Mich			
For corne 多色 CTION			[es]	r F	
(County)	Located in:	Corner Code #	AYEO	5	.
1. Public Land Survey	T 14N R 3E	(M-9)	NN03	· 6	RECORDED
	T <u>14N R 4E</u>	A.9	77.0	2.	OR C
	<u>T</u> R		WICHIGAN	35 20	330
2. Property Controlling	S T R		HE	18. HM	
in Section	s T R		MAS	9	
3. Miscellaneous	S T R			R	
Property in Sec.	STR		Register of Deeds Stamp &	File Number	
Lot No, Recorded P Private Claims	lat				
			ABCDE	FGHI	JKLI
I, JERRY L. JONES, in a field survey or	n <u>July 15</u> , 19 <u>97,</u> do hereby ce	ertify	2 6 5	43-	
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned on			3	$\dot{1} + \dot{1} +$	- - -
lines 1 and 2 above were in conformance with regulations and rules therefore as required			4 - 7 - 8 -	9-10-	-11-12
in the current manual of survey instructions of the United States Department of the interior, Bureau of Land Management or by a decree of a Court of Law and/or that the			5	 	
corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules			1 . 1 . 1	16-15-	-14-13-
of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; re-established,			7 - 1 - 1 - 1 - 1		- - - -
monumented, re-monumented, recove	red, found as expressed below	v:	8 -19 - 20 -	21 - 22	-23 - 24
			" I I	2827-	-2625-
NOTE: Not more than 2 corne	ers, all in the same town	and range, may be	11	20 27	1 1
recorded on this certif	icate.		1 ' 1 ' 1	33 - 34	-35 - -36-
A. Description of original monu-	ment and accessories an	d/or subsequent resto	13 L L L L L L L L L L L L L L L L L L L	1 1 1	
		·		0	MOLAN INC.
M-9/A-9 Corner common to Sections	24, 25 T14N-R3E and 19, 30 T	14N-R4E		STATEO	F MICHIGA
Government survey, set post	1932 I Wampler			6	
	ring, 1971, 1976, found 3/8" re	arod L-864 P 105 and L-705	Dam / //		RRYL.
Survey by Burgin Land Surve	ys, 1990, found 3/8" iron rod,	L-1220. P-43		1 1	ESSIONAL
				SUF	RVEYOR /
WITNESS NOTE: Witnesses fro	m above surveys and LC	RC's are available in do	ossier file; which was	ST. W. N	No. 9838
presented to	peer review committee a	nd is on file at the Regi	ster of Deeds Office.	A Paris	W- 7.
B. Description of corner evidence	ce found and/or method	applied in restoring or	reestablishing corner:	PROF	ESSION P
M-9/A-9 Corner common to Sections					
round 5/8 reloa dirtop di 1	pipe per surveys by Edmands	s Engineering and Burgin La	nd Surveys		
2.5					
C. Description of monument for	corner and accessories	established to perpetua	ate locating the position of	the corner:	
M-9/4-4 Corner common to Sections 2	24, 25 T14N-R3E and 19, 30 T1	4N-R4E			
Found 3/8" rerod per surveys	by Edmands Engineering and	Burgin Land Surveys, rente	ced rerod with 5/8" rerod and b	ace nan etama	and Bou Court
Remonumentation PS 19838	in mon box, and is accepted a	s the best available evidence	e of the position of the accepted	corner.	ed, Day Gount
N 60 Deg E, 20.03', nail and B	lav County disc in guard rail s	nst (R)	APPROVED LAND CO	IDNICO	
N 60 Deg E, 20.03', nail and Bay County disc in guard rail post (R) N 45 Deg W, 12.23', nail and Bay County disc in guard rail post (R)		P.A. 345 OF 1990 - Ba	y County		
N 40 Deg E, 31.96', nail and Bay County disc in fence post		Date 27 Junes	7		
N 52 Deg E, 21.52', pk nail in top of old guard rail post (R)			Michael MacDonald P	<u>s</u> .	
N 62 Deg W, 62.41', pk nail in	telephone pole (R)		County Representative	B	
Signed by	ungh. De	Dat	e/0/2Z/	97	
Surveyor's Michigan License No.	19838	Form approved b	y Michigan State Board of Land	Surveyors, Jar	1. 28, 1971

35 004

20

Revised May 14, 1971 Revised Jan., 1983