SUHVEY & REMONUMENTATION

APR 2 3 1998

SECTION

REMON COR. M-7, WILLIAMS TWP LAND CORNER RECORDATION CERTIFICATE

For corners in		Filing Requi	rement of Act 74, Mic	h. P.A. 1970				
Bay				1		_ K		
(County)		Located in:	Corner Code #			AKC:	Nov 10	
1. Public Land Su	rvey	T <u>14N R 3E</u> T <u>14N R 4E</u> T R	M-7 A-7			STER OF DOUNTY. MIC	7 29	RECORDED
 Property Control in Section Miscellaneous Property in Sec 	\$	T R T R T R T R T R T R T R T R T R T R		Register of I	Deeds Sta	EEDS File	Number	J
4. Lot No. 5. Private Claims	, Recorded Plat			A B	S C D		. н т	JKLI
ines 1 and 2 above we in the current manual interior, Bureau of Land corner points mentione of the Michigan Board of the Michigan Bo	ts of P.A. 74, Michigan ere in conformance with of survey instructions of Management or by a ed in lines 3, 4 and 5 a for Land Surveyors or burnented, recovered, for than 2 corners, all on this certificate. The priginal monument and the survey, 1839, set post, Closek, 1984, found incore in conformation of the corners, and survey, 1839, set post, Closek, 1984, found incore in conformation of the conform	P.A. of 1970, the corner regulations and rules of the United States of the United States. decree of a Court of above were in conformy a Decree of a Court and as expressed below in the same town and accessories and J. Mullett on, L-962, P-725 and 1/2" iron, L-1035, Ind 1/2" i	er points mentioned on stherefore as required Department of the Law and/or that the mance with the rules of Law; re-established, ow: n and range, may be and/or subsequent restablished.	26 3 47 5 61 7 81 9 103 11 123 13	9-20 0-29 1-32		3-10-10-	-21
WITNESS NOTE: V	Nitnesses from abo presented to peer i	ove surveys and LO review committee	CRC's are available in d and is on file at the Reg	lossier file; whi jister of Deeds	ch was Office.		IERI 401 PROFES	IY L. NES SIONAL
B. Description of c	orner evidence fou	nd and/or method	d applied in restoring or	r reestablishing	corner	ACT.	sunvi N i	EYOR J
M-7/ A-7 Corner comm						LICENST	PAOFES	o. 338 SIONAL
Found 1/2" ro	od with stones around p	per surveys by P. Clos	ek, D. Burgin and L. McGinn	is			and the second	A Parket
C. Description of m	nonument for corne	er and accessories	s established to perpetu	ate locating th	e positi	on of the	corner:	
M-7/A-7 Corner comm	on to Sections 13 and	14, T14N-R3E & 18 an	id 19, T14N-R4E					
Found 1/2" ro Ciosek, D. Bu	od, replaced 1/2" rod w rgin and L. McGinnis a	ith 5/8" rod and brass nd is accepted as the	cap stamped Bay County R best available evidence of th	emonumentation te position of the a	PS 19838 accepted	in mon bo corner.	x, per sur	veys by P.

East, 44.62', center line top telephone box (R)

N 45 Deg E, 103.2', SW corner house #4489 (R) N 25 Deg E, 114.70', center line top hydrant (R)

\$ 80 Deg W, 37.25', nail and disc in power pole (R)

East, 11' to centerline of 8 Mile Road

Surveyor's Michigan License No. 19838

APPROVED LAND CORNER
P.A. 345 OF 1990 - Bay County
Date 27 June 57
MTM
Michael MacDonald P.S.
County Representative

Signed by

10/22/97 Date

Form approved by Michigan State Board of Land Surveyors, Jan. 28, 1971 Revised May 14, 1971

Revised Jan., 1983