Bay County Remonumentation

LAND CORNER RECORDATION CERTIFICATE

p	Filing Requirement of Act 74, Mich. P.A. 1970											
F0I	corners in Bay (County)	Locat	ed In:	Corner (Code #	1			3 <u>3</u>	1		
	, ,							NE GI	£ 22			
1.	Public Land Survey		14N R 4E	<u>J 11</u>				SEE S	ī		REC	
		Т	R R					* OF %	ن س س	,	RECÒRDED	
2.	Property Controlling	ST	R			003	256	DEEDS	3		G3	
2	in Section Miscellaneous		RR			400	AUU	*	` £			
Property in Section S T R Register of Deeds Stamp & File											nber	
4	Lot No,	Recorded Plat										
	Private Claims						A B		F G		J K	
							3 3			3		
							4-7-		-9	10	111	
۱, C	raig W. McVean hereby certify that under re	_ , in a field surve	ey on April 5	of 1070, the co	, 19	95	5	+++	++-	\vdash	 	
in li	ines 1 and 2 above were in	conformance wit	th regulations and rul	les therefore as I	required in ti	he current	6 18	17	16	15	14	
	nual of survey instruction nagement or by a decree of						819	-20	21	22	23 2	
5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found							9	 	1-		1	
	cree of a Court of Law; est expressed below:	adiished, re-esta	ibiished, monumente	3u, re-monumen	itea, recover	ea, iouna	10 30	29	-28	27	26 2	
NC	NOTE: Not more than 4 corners, all in the same town and range, may be recorded								++		•	
	on this certificate.						13 31	32	33	34	353	
A.	Description of origina	i monument ar	nd accessories an	d/or subsequ								
	<u>J 11</u> - Set 1/4 Section po	st - J. Mullett - 1	1 840.			<u>Surveys</u> - L. 66 uction joint - D						
	Elm 9" N 10° E 8 Lks. Maple 6" S 47° W 4 Lks.		1974; L. 79	98, P. 628 - four	d nail - 197	'6; L. 808,	P. 468 -	found	nail -			
McGinnis - 1985; L. 1047, P. 310 - found							found "T"	' iron in	monu	ment		
	<u>Bay County Road Commission Witness Book</u> - Witnesses - No date.					y - 1984; L. 129 der - 1993.	7, P. 382 -	touna "	' iron in	monu	ment	
											,	
В.	Description of corner	evidence foun	d and/or method	applied in res	toring or re	establishing	corner:					
	<u>J 11</u> - Found "T" iron in monument box per recorded surveys 1984 and later. This position replaced the nall that was obiterated during sewer line construction. Monument is 1'± N of physical centerline E-W Road and on centerline ditch to N. Found recorded witness as follows:				NE 37.83' (37.5' - R) (36.45' - B.C.R.C.) to face U.P. SE 50.35' (50.37' - R) to face U.P.; 50.95' (50.6' - R to nail) (51.0' to B.C.R.C.) To Pk in U.P. W 24.2' (24.18' - R, 24.1' - R) to E edge MH, 25.35' (25.32' - R) to centerline MH. Monument accepted as the best available evidence of the position of the original corner.							
			í									
			·			APPROVED LA P.A. 345 OF 19	90 - Bay Cou					
						Date <u>6 J</u> <u>MJM</u>	01/ 82					
	·		,			Michael MacDo County Represe	manath					
c.	Description of monun	nent for corner	and accessories	established to	perpetua	te locating the	position	of the or		.		
	J 11 - Replace "T" iron - on 5/8" x 24" rebar in mo	io iong with z i	/2" Bay County bras	ss cap				A Proposition		CAN		
	I 37° E 38.25' to set nail and tag in NW side U.P. 5 40° E 50.89' to set nail and tag in NE side U.P. 5 12° E 34.61' to chiseled "+" on NNW face concrete sanitary pump tation MH. I 80° W 24.22' to chiseled "+" on E rim sanitary MH.						* LICE	MC PROFE SUR	NG W. VEAN SSIONA VEYOR No. ROSB			
	S 23° W 29.59' to chisele		_			,		ED AR OFE	SSION	60	,	
Sia	ned by <u>Carry</u> rveyor's Michigan Licer	W. W.	ne Veur		Dat	te /2//:	9/95					
Sui	rveyor's Michigan Licer	nse No. 3 '	7088			RM APPROVED BY MICH	IGAN STATE BO	ARD OF PROFES	SIONAL SUR	VEYORS, J	AN. 28, 1971	

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983