SECTION

BAY COUNTY REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74 Mich. P. A. 4070.

2CONN	Filing Requi	irement of Act 74, Mi	ch. P.A. 1970	•		
For corners in BAY COUNTY (County)	ocated In:	Corner Code #		REGISTE BAY COUN	2000 JAN	R E
	14N R _ 5E R R	D-7		R OF DE	ط ا - ۱	CORDE
3. Miscellaneous ST_	R R R R R			EDS Register of De	2: 00 eeds Stam	O & File Number
4. Lot No, Recorded Plat _						
5. Private Claims			1 2	B C D E	FGI	JKL
	· · · · · · · · · · · · · · · · · · ·		3	Ĭ		
I, DALE L. WINIECKE, in a fix state that under requirements of P.A. 74, Milines 1 and 2 above were in conformance we current manual of survey instructions of the Ur Management or by a decree of a Court of Law and 5 above were in conformance with the red Decree of a Court of Law; established, re-estableow:	chigan P.A. of 19 ith regulations and ited States Depart and for that the cules of the Michiga	70, the corner points med rules therefore as requinant of the Interior, Burer orner points mentioned in Board of Land Surveyo	ntioned in red in the 6 au of Land 7 lines 3, 4	-18 -17 -19 -20	9 - 1	2-2324-
NOTE: Not more than 2 comers, all in the sa on this certificate.	me town and rang	e, may be recorded	11	111		
			12	31 32	33 3	1 35 36
A. Description of original monument and	accessories and/	or subsequent restorat	ion:			
D-7 POST SET BY J. WAMPLER, 1821 16" SUGAR MAPLE N47°E 18 LINKS 6" SUGAR MAPLE S58°W 20 LINKS						
-CERT OF SURVEY L. 673, P. 266, 1972, L. M -CERT OF SURVEY L. 840, P. 596, 1978, L. M -CERT OF SURVEY L. 893, P. 544, 1980 M. M	cGINNIS, PS #189	9, FND PK NAIL.				
-PLAT OF McNEILL, LEWIS AND COMPANY'S			RDS.			
B. Description of corner evidence found	and/or method a	pplied in restoring or re	establishing corn	er:		
D-7 SEARCHED THE APPARENT LOCATION OF THI CHECKED WITNESS FROM THE SOUTHWESTE FACE OF 30" MAPLE; NORTHEAST 31.1' TO F 0.82' TO MH RIM (M).	RLY NAIL TO THE	ABOVE SURVEYS NORTH	HWEST 33.75' TO FACE OF U. POLE	18" MAPLE (R (M); SOUTHW	t), NORTHV /EST 0.25'	VEST 33.9' TO TO MH RIM (R);
THE SOUTHWESTERLY PK NAIL WAS ACCEPT	ED AS THE BEST	EVIDENCE OF THE POSIT	ION OF THE ORIGI	NAL CORNER.		•
C. Description of monument for corner an	d accessories es	tablished to perpetuate	locating the pos	sition of the co	orner:	,
D-7 REPLACED THE PK NAIL WITH 5/8" X 24" LON S70°W 42.06' SET NAIL AND TAG IN EAST FA N40°W 34.20' SET NAIL AND TAG IN EAST FA N40°E 31.60' SET NAIL AND TAG IN NORTHW S40°W 43.00' TO THE TOP CENTERLINE OF H S40°E 35.47' SET NAIL AND TAG IN WEST FA SOUTH 1.20' TO THE PHYSICAL CENTERLINE OF NE 0.88' TO FOUND SMALL PK NAIL	ACE OF 12" MAPL ACE OF 24" MAPL /EST FACE OF U. I YDRANT AT SOUT CCE UTILITY POLE	E E POLE THWEST QUADRANT	ntation cap in	MONUMENT B	DALE WINIEC PROFESSI SURVEY No.	L. * * * * * * * * * * * * * * * * * * *
D. 1. 11) -	l				4191:	5 SURPLY
Signed by <u>All Wurs</u>	. –		Date	12/30/8	FESSI	O to by the same
Surveyor's Michigan License No. <u>4</u> B WT1999, P. 2	1915 APPROVED LAND P.A. 345 OF 1990	Ray County		·		
	Date O9.30.9 M H Michael MacDonal		NOVED BY MICHIGAN ST	THE BOARD OF PROP	, ,	VEYORS, JAN. 28, 197 REVISED MAY 14,197 REVISED JAN., 198 REVISED OCT., 199