BAY COUNTY REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74. Mich. P.A. 1970

For corners in	i milg itedulien	ent of Act 74, Mich. P.A. 13,	/U ∽=		
BAY COUNTY	Located in:	Corner Code #	REGIS BAY COI	2000 JAN	22
1. Public Land Survey	T <u>14N R 5E</u> T R T R	D-9	SIER OF DUNITY MA	O	RECORDE
2. Property Controlling S in Section S	TR		Wollo Solid	5 5	וח ם
3. Miscellaneous S. Property in Sec. S.	TR		Ž	0	
rioperty in ode.	- ' '\		Register of De	eds Stamp &	File Numb
4. Lot No, Recorde	ed Plat				
5. Private Claims		-	ABCDE	FGH	JK
			3 6 5	-43	2
I, DALE L. WNIECKE, that under requirements of P.A. 74 and 2 above were in conformance manual of survey instructions of Management or by a decree of a Co and 5 above were in conformance Decree of a Court of Law; establish below:	, Michigan P.A. of 1970, the com- with regulations and rules thereign the United States Department of burt of Law and /or that the corner with the rules of the Michigan Bo ed, re-established, monumented,	ner points mentioned in lines 1 fore as required in the current fore as required in the current fore interior, Bureau of Land points mentioned in lines 3, 4 and of Land Surveyors or by a recovered, found as expressed	4 7 8 5 6 18 17 7 8 19 20 9 10 30 29	- 9 10 15 15 21 22 27 28 27	21 -26 -2
NOTE: Not more than 2 corners, a on this certificate.	all in the same Town and Range, n	nay be recorded	11 12 31 32	-3334	35_3
			13		
A. Description of original monu	ment and accessories and/or s	ubsequent restoration:			
D-9 POST SET BY J. MULLETT, JUNE 18 40" WHITE PINE N 12°W 7 LINKS 36" BLACK OAK S 12°E 26 LINKS	339				
CERT OF SURVEY L.1491, P.691, 1 CERT OF SURVEY L.772, P.149, 19 CERT OF SURVEY, UNRECORDED, J CERT OF SURVEY L.843, P.572, 19 CERT OF SURVEY L.799, P.630, 19	75, L. McGINNIS, PS#18999, NO IOB #2108, H.J. EDMANDS 1963 78, L. McGINNIS, PS#18999, NO	CALL. , PS#3699, NO CALL. CALL			
PLAT OF ZAGELMEYER AND CO'S F PLAT OF FISHER AND VAN LIEW'S PLAT OF HW SAGE'S THIRD ADDIT	ADDITION, L. 2, P. 46, BAY COL	INTY RECORDS			
-	ce found and/or method applie	d in restoring or reestablishing	corner:		
D-9 SEARCHED THE APPARENT LOCATI VERIFIED THE LOCATION ACCORDI PK NAIL WAS ACCEPTED AS THE B	NG TO THE RIGHT-OF-WAYS AS	SHOWN ON THE ABOVE MENTIO	NED SURVEYS.		÷
C. Description of monument for	corner and accessories establ	ished to perpetuate locating th	e position of the co	orner:	
D-9 SET 5/8" x 24" REROD WITH BAY C N 65°E 93.40' TO SW CORNER HOL S 30°E 42.30' TO NAIL AND TAG IN S 35°E 76.25' TO NW CORNER BRIC S 50°W 72.30' TO NE CORNER HOL N 40°W 48.00' TO SE CORNER BUIL N 35°W 34.44' TO TOP CENTER OF	JSE # 101 SOUTH WENONA. I NE FACE 36" MAPLE. CK PILLAR HOUSE #701 SOUTH \ JSE # 700 SOUTH WENONA. LDING # 616 SOUTH WENONA.		W W	OF MICHIGA DALE L. VINIECKE DESSIONAL URVEYOR	MANAGE HOL
	•	APPROVED LAND CORNER P.A. 345 OF 1990 - Bay County Date	THE SOLL OF THE PARTY OF THE PA	No. 41915 ESSIONA	ST. HAR.
D. Va	Wineste	Michael MacDonald P.S. County Representative	alanh	()	٠
		Dat	te 15/30/8	J	_
Surveyor's Michigan License N	o. <u>41915</u>		.•		

FB WT 1999, P.8