1996 BAY COUNTY REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

A STATE OF STATE OF STATE

003 334

For corners in			1		
Bay (County)	Located In:	Corner Code #	BAY (Dec 2	
1. Public Land Survey	T <u>14N.</u> R <u>6E.</u> T <u>14N.</u> R <u>6E.</u> T R	C-12 C-13	SOUNTER	7 24	RECORDED
Property Controlling S in Section S	T R T R		MICHIOAN	42 M 96)ED
3. Miscellaneous S Property in Sec. S	T R		•	¥ 62	
r ropony in oco.		· · · · · · · · · · · · · · · · · · ·	Register of	Deeds Stamp & I	File Number
4. Lot No, Recorded 5. Private Claims	Plat		A B C D	EFGHI	Экг
			2 6 5	4	-2-1-
			3		
I, Ronald C. Prevost, in a field survey on 4-30, 19 96 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law			5	9 10	1112-
and /or that the corner points mentione Michigan Board of Land Surveyors	ed in lines 3, 4 and 5 above wer	e in conformance with the rules of the	, , , , , , , , , , , , , , , , , , , ,	1615	-1413
monumented, recovered, found as exp	ressed below:	or zam, obtablionos, to obtablionos	8 19 20	2122	2324
NOTE: Not more than 2 corners, a	ıll in the same town and ranç	ge, may be recorded	9		
on this certificate.			103029-	28 27	2 ⁶ 2 ⁵
A Description of outstant in the			11 31 32	1 22 24	1 1
A. Description of original monum	ent and accessories and/or	r subsequent restoration:	12 31 32-	33 34	3536-
Recorded survey L832 P177 L.C.R.C. L2 P564 boat spike Recorded survey L1215 P28 McGinnis 1992 B. Description of corner evidence	e/mon box, Leach, 1984 36 5/8" bar/mon box	blied in restoring or reestablishing	/2" bar/MB B.D. Ferg	35011, 1004	·
C-12 Found boat spike in mon b		_	•		
On line between C-11 & C- 1958 North 2633.69 (2633.22R) South 2633.51 (2633.22R) N.60°E. 36.90 (36.95R) L2 T.P. (P.P.R) N.70°E. 36.6 (36.8R) L832 32.1 SW. to end C.M.P. (35.8 SE. to end C.M.P. (35.8 SE. to face U, Pole (34.8 Approved by Peer Group 65.8 SE. To end C.M.P. (35.8 SE. To end C.M.P. (35.8 SE. To face U, Pole (35.8 SE. To face U) (35.8 SE. To face U)	13, as per Con. Pwr. Co. Con. Pwr. Co. 1958 Con. Pwr. Co. 1958 P564 nail SE (NE.R) face P177 face T. pole 2.1R) L1215 P286 S.8R) L1215 P286	NE. 47.0 (47.0R N.30°W. 74.7 (7 N.45°E. 47.43 (4 S.30°W. 75.12 (S.45°E. 51.46 (5	n mon box 5R L832 P177) E. leg I L832 P177) to T. po 74.7R L832 P177) to 1 47.46 L3 P79) N/S SI (75.12R L3 P79) N/S 51.46 R L3 P79) 1/2" er Group 6-27-96	le face 8" Pine E face P pole E. face P. pole	
C. Description of monument for co	orner and accessories lesta	ablished to perpetuate locating th	e position of the corn	er:	
C-12 Replaced boat spike with 5/4 existing mon box 9-30-96. N.60°E. 36.90 nail SE face 32.1 SW. to end C.M.P. 35.8 SE. to end C.M.P. 36.6 NE face U. pole. North 2633.69 to corner C-1 South 2633.51 to corner C-1	T. pole.	mon box. 7 N.45°E. 47. N.40°W. 75 Re-mon dis S.30°W. 75 S.45°E. 51.	43 N/S SE face P. pc i.24 N/S W. face 14" l	ole. Pine. Reset Bay (Co.
0 11	20 1		Í	* PREVO	ST Jo
Signed by Konald C.	Mens	Date /	2-23-96	- PROFESS!	
Surveyor's Michigan License No.	24612			SURVEY	VA Jak
· ·		APPROVED LAND CORNER P.A. 345 OF 1990 - Bay County Date 27792 96 /// // Michael MacDonald P.S.	APPROVED BY MICHIGAN STAT	POFESSIN	NAL SURVEYORS, ISED JAN 28, 1971 ISED NAY 14, 1975 IEVISED JAN, 1983 EVISED OCT., 1995

Michael MacDonald P.S.