1 3 4 3 5 7 6 - 4 8 No TEMORUSHIEN

MAY 2 0 1997

1996 BAY COUNTY REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970.

1365 W. C.	Filing Requ	irement of Act 74, Mich. P.A. 1	970		
For corners in		1		003	331
Bay (County)	Located In:	Corner Code #	B A	景 景	
1. Public Land Survey	T <u>14N.</u> R 6 E. T <u>14N.</u> R 6 E. T R T R	F-11 F-13	A COMEN. HICHIC	175 201	RECORDED
2. Property Controlling Sin Section S	T R T R T R T R		2	% & &	DED
4. Lot No, Recorded Pla 5. Private Claims	l		АВСІ	O E F G H	IJKI
o. Firvate claims			2 6 3	5 4 3	3-2-1
I, <u>Ronald C. Prevost</u> , in a field survey on <u>7-6</u> , 19 <u>96</u> do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:			4 7	8 9 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	0 11 12 13 5 14 13 2 2 23 24
NOTE: Not more than 2 corners, all in on this certificate.	the same town and rar	nge, may be recorded	9 10—30—2 11 12—31—3	9 28 2	7 26 25
A. Description of original monument	and accessories and/	or subsequent restoration:	13		
F-11 Post set by Risdon, 1834 No Pt. set by Cons. Pwr. Co. 19 No Pt. shown as set in Wade Tr Rec'd survey L869 P264, 3/8" ir Rec'd Survey L900 P682 iron N Rec'd survey L1083 P275 3/8" i. LCRC L2 P624 fnd boat spike ra 1989	im info. on Closek, 1979. /IcGinnis 1981. ron Ledy 1987.	G-13 L.C.R.C. L3 I	Vampler, 1821 by Con. Pwr. Co. 1 P85 1/2 bar, 1994		oportion E-13 &
3. Description of corner evidence for	und and/or method ap	plied in restoring or reestablishing o	corner:		
F-11 3/4" pipe set midway between E- Pwr. Co. & Wade/Trim) 7-6-96 South 6.8' chisled cross on W. e. N.15°W. 59.4 face U. pole (60.1: P682)(L1083 P275) N.50°E. 90.05 face U. pole (90.3 P682)(L1083 P275) Approved by Peer Group 8-8-96.	Agrees with L Is very near t Co. W. 2641. Approved by	F-13 Found 1/2" bar in mon box 7-6-96. Agrees with L.C.R.C. L3 P85. Is very near to single proportion location as per Cons. Pwr. Co. W. 2641.96, E. 2642.36. Approved by Peer Group 8-8-96.			
C. Description of monument for corne	r and accessories est	ablished to perpetuate locating the	position of the cor	ner:	

F-11 Replaced 3/4" pipe(B-above) with 36" X 5/8" Re-rod with Bay Co. Re-mon cap. 10-10-96.
South 6.8 chisled \Box on W. end 60" R.C.P. N.15°W. 59.40 face util. pole. N.50°E. 90.05 face util pole. S.70°E. 42.80 cut + E. end 60" R.C.P.

F-13 Replaced 1/2" bar with 5/8" bar, Bay Co. Re-mon cap in existing mon box, 10-3-96.

N.35°W. 48.70 R.R. spike SE face T. pole.
S.45°W. 93.45 N/S SE face power pole.
S.15°W. 64.25 NW cor. house #232. S.15°E. 58.84 NE cor. house #232



Surveyor's Michigan License No. 24612