SURVEY & REMONUMENTATION

APR 2 6 1995

COMMISSION

Bay County Remonumentation

Nov 21 3 48 PH '94

RECORDED

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Bolimar Glas & Philaster 1940

For corners in Bay			,	REGISTE OF DEFOS BAY COLOR - KICKDAN
		Located In:	Corner Code ≠#	
	(County)			
1.	Public Land Survey	T.15N.R.3E.	K 13	
		T R		Mark Name
		Τ		8 003 116
		T R		
2.	Property Controlling	S R		
	in Section	S R		
3.	Miscellaneous	S T R		Register of Deeds Stamp & File Number
	Property in Sec.	S	an complete that and a description of the descripti	Transfer of Books Grant & The Namber
4.	Lot No.	, Recorded Plat		A R C D F F G H I I K

, 19 94 t, Craig W. McVean ... , in a field survey on ... June 13 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below: NOTE: Not more than 4 corners, all in the same town and range, may be recorded

on this certificate.

Description of original monument and accessories and/or subsequent restoration.

K 13 Set Post - H. Parke - 1831. Hemlock 15" N 87° E 30 Lks. Hemlock 8" N 67-1/2° W 10 Lks.

BCRC witness book - 1/2" rod - 1970. Recorded Survey - L. 680, P. 168 - Found 3/4" re-rod - 1972. 10

Description of corner evidence found and/or method applied in restoring or reestablishing corner;

K 13 Standard Section corner common to Section 35 and 36, T15N, R3E - Found 5/8" rebar (3/4"-R) per recorded survey at occupation line to North. Found recorded witness as follows: S 60° E (R) 62.7' (62.15' -R) to face base fence corner (appears newer). Monument accepted as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

K 13 Excavate around straight 5/8" rebar - Set 2-3/4" Bay County brass cap on existing 5/8" rebar and place mon. box. N 35° E 30.30' to nail and tag in SE. side U.P. N 20° E 49.85' to nail and tag in W. side 24" poplar. N 27° W 97.93' to SE. corner of plastic siding on House #506. N 45° W 137.42' to SW corner of plastic siding on House #506. East 20.46' (M & GLO) to set capped 3/8" rebar at K 1-T14N-R3E.

Michael MacDonald P.S. **County Representative** Date //-10 94

OF MICHIGAN CRAIG W. **McVEAN** PROFESSIONAL SURVEYOR No. 39088 POFESSION

Burveyor's Michigan License No.

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN 28, 1971