MAY 2 0 1997

CONCRE

REMON. COR. H-11, GARFIELD TWP. LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74. Mich. P.A. 1970

008	3
-----	---

298

For corners in Bay	i iinig ricqui	ioment of Aut 74, imo	1		
(County)	Located in:	Corner Code #			
1. Public Land Survey	T <u>16N</u> R <u>3E</u> T R T R	<u>H-11</u>	NULS 188		22
 Property Controlling in Section Miscellaneous Property in Sec. 	S T R S T R S T R		Register of Deeds Stappe &	ile Number	RECORDED
Lot No, Recorded P Private Claims	lat	***		FGHI	JKLI

I, <u>JERRY JONES</u>, in a field survey on <u>OCT 1</u>, 1996, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned on lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

- 2 4 5 ìя 6 15 16 7 19 8 ຂໍດ 21 22 23 9 10 Ż8 **2**7 29 26 11 12 13
- A. Description of original monument and accessories and/or subsequent restoration:
- H-11 Corner common to Sections 27 and 34
 - GLO, set post, H. PARKE, 183015
 - 1909, C. Thornthwaite, found post
 - 1972, L. McGinnis, rec survey, L-691, P-611, mon box
 - 1973, L. McGinnis, rec survey, L-716, P-549, found mon box
 - 1973, L. McGinnis, LCRC, L-1, P-591, mon box
 - 1974, L. McGinnis, rec survey, L-735, P-574
 - 1977, Edmands Engineering, rec survey, L-815, P-432
 - 1980, E. Goss, rec survey, L-897, P-315
 - 1982, R. L. Merry, rec survey, L-922, P-714
 - 1984, R. L. Merry, rec survey, L-1039, P-881
 - 1986, D. Burgin, rec survey, L-1035, P-542, 1/2* iron in mon box
 - 1986, D. Burgin, rec survey, L-1035, P-536, 1/2* ion in mon box
 - 1988, P. Ciosek, rec survey L-1096, P-630, mon box
 - 1989, M. MacDonald, rec survey, L-1115, P-870, found mon box
 - 1989, P. Ciosek rec survey, L-1115, P-930, iron in mon box
 - 1995, L. McGinnis, rec survey, L-1373, P-493, found mon box

APPROVED LAND CORNER
P.A. 345 OF 1999 - Bay County
Date <u>/6 Oc. 196</u>

Michael MacDonald P.S.
County Representative



WITNESS NOTE: Witnesses from above surveys and LCRC's are available in dossier file; which was presented to peer review committee.

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- H-11 Corner common to Sections 27 and 34

Found re-rod in mon box per surveys by O. Thornthwaite, L. McGinnis, Edmands Engineering, E. Goss, R. L. Merry, D. Burgin, P. Ciosek, M. MacDonald and LCRC by L. McGinnis

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- H-11 Corner common to Sections 27 and 34

Found re-rod in mon box per surveys by L. McGinnis, Edmands Engineering, E. Goss, R. L. Merry, D. Burgin, P. Giosek, M. MacDonald and LCRC by L McGinnis, replaced re-rod with 5/8" rod and brass cap stamped Bay County Remonumentation PS 19838, and is accepted as the best available evidence of the position of the accepted corner.

South, 49.66', nall and BC disc in power pole (1986 wit.) S 25 Deg E, 48.49', centerline 4" steel pipe gate post (1986 wit.) S 60 Deg E, 150.46', nail and BC disc in power pole (1986 wit.) N 65 Deg W, 196.45', nail and BC disc in power pole South, 8.0', centerline bit road (1973 wit.)

Signed by Sang J. Sonce Date

Date 11/27/96