For corners in  BAY COUNTY (County)  1. Public Land Survey  2. Property Controlling S in Section S	LAND CORN	COUNTY REMONUMENTATION CERTIFICER RECORDATION CERTIFICEMENT Of Act 74, Mich. P. Corner Code #	IFICATE	REGISTER OF DEEDS BAY COUNTY, MICHIGAN	Dec 30 3 39 PK '97	RECORDED
3. Miscellaneous S. Property in Sec. S.		**************************************	Post	ston of Doods	. 64	File Normalis
			Regi:	ster of Deeds	Stamp &	riie Number
4. Lot No, Recorde	ed Plat		A B	CDEF	F G H 1	I J K L
5. Private Claims			26-	5	3	2l
			3 4 7-	8	910	1112
I, Paul M. Ciosek, in a fir requirements of P.A. 74, Michigan F were in conformance with regulation instructions of the United States C decree of a Court of Law and /or the conformance with the rules of the Law; established, re-established, re-	P.A. of 1970, the corner points and rules therefore as requestment of the Interior, Boat the corner points mention Michigen Board of Land Sur	nts mentioned in lines 1 and 2 ab uired in the current manual of su Bureau of Land Management or I ned in lines 3, 4 and 5 above we veyors or by a Decree of a Cou	rvey 6 18- by a 7	20 2	122-	1413 2324
NOTE: Not more than 2 corners, a on this certificate.	all in the same town and ran	ge, may be recorded	10-30-	29-2	827-	2625
Ori ens Cardicale.			11 -31-	32-3	3-34-	35-36
A. Description of original monutions K-9 1. SET POST J. MULLETT D.S., RE HEMLOCK 10* N 85°E 21 LINK ELM 12* S 22°W 22 LINKS  2. LCRC, L. 1, P. 477, GOSS, (12/ 3. LCRC, L. 001, P. 567-568, SCH 4. SURVEY, L. 719, P. 332, SCH 5. SURVEY, L. 735, P. 560, MCGI 6. SURVEY, L. 735, P. 562, MCGI 7. SURVEY, L. 784, P. 167, MCGI 8. SURVEY, L. 900, P. 669, MACI 9. SURVEY, L. 939, P. 495, JONE 10. SURVEY, L. 951, P. 418, MCGI 11. SURVEY, L. 1135, P. 274, BUR 12. SURVEY, L. 1325, P. 759. MCGI	ESURVEY 1846 S /23/72), FND 5/8" ROD HAFER, (5/4/73), FND 1/2" f NFER, (9/19/73) NO CALL INNIS,(4/2/74) FND 5/8" BAI NNIS,(4/2/74) FND 5/8" BAI NNIS,(4/6/76) FND 5/8" BAI DONALD,(3/2/81) FIELD NO' S,(6/7/83) FND 1/2" ROD NNIS,(10/21/83) FND 5/8" E GIN,(11/20/89) FND 1/2" IR	ROD R R R R TES FND 5/8" IRON BAR				
B. Description of corner evider	nce found and/or method	applied in restoring or reestab	lishing corner:			
K-9 SEARCHED THE APPARENT LOCAT ROAD SURFACE 5/8" REROD GOES POSITION OF THE ORIGINAL CORN	SINTO 2" PIPE. ACCEPTED ER.	THE FOUND 5/8" REROD IN 2"	PIPE AS THE BES	T AVAILABLI	E EVIDENCE	
	for corner and accessorie	es established to perpetuate l	ocating the posi	tion of the c	orner:	
K-9 DROVE DOWN THE 5/8" REROD IN MONUMENT BOX N 50° E 30.66 SET 3/8" CAPPED IR S 48° E 30.18 SET 3/8 CAPPED IR S 25° W 39.29 PK/REMON PK & TA S 42°W 80.47 (80.3 R) REMON TA S 51°W 33.11 SET 3/8" CAPPED IR N 48° W 26.12 SET 3/8" CAPPED IR N 45°W 33.95(34.00° R.) SOUTHEA	RON ON AG IN W. END 42" CMP G NORTHWEST FACE OF PO RON RON	OWER POLE  OF MICA		. ,		
FIELD BOOK , PAGE 5 P.	No. 35835 PROVED LAND CORNER A. 345 OF 1990 - Bay County ate 37June 97 The Chael MacDonald P.S.	25835		Date		