BAY COUNTY REMONUMENTATION 1998 LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

ro	r corners in			Ingq BAY
_	BAY (County)	Located in:	Corner Code #	<u>ව</u> නි. උ
1.	Public Land Survey	T <u>17N_R_3E</u> TR		COR FROF
2.	Property Controlling	STR		DEI O
3.	Miscellaneous	STR		DO) (c.)
	Property in Sec.	STR		N 6 05
4.	Lot No, Recorded Plat			Register of Deeds Stamp & File Number
	Private Claims	corded Plat		A B 0 B 5 5 5
l, <u>E</u>	<u>3RIAN D FERGUSON</u> , in a f	ield survey on OCTORER	19 00 de bando esta d	3 4 7 8 9 10 11 12
requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:				6 18 17 16 15 14 13 - 7 8 19 20 21 22 23 24 -
NOT	TE: Not more than 2 c on this certificate.	orners, all in the same town	and range, may be recorded	9 10 30 29 28 27 26 25 11 12 31 32 33 34 35 36
Α.	Description of original m	onument and accessories an	d/or subsequent restoration:	13
	Description of original monument and accessories and/or subsequent restoration:			
	WOOD POST SET BY H. PARKE IN 1831 10" BEECH S42E 58 LINKS AND 10" BEECH N34E 57 LINKS SLICVEY &			
	LCRC'S REC IN L. 001, PG, 553 AND L. 002, PG, 504			SURVEY & REMONUMENTATION
	SURVEY'S REC IN L. 811, PG. 110; L. 876, PG. 294 AND L. 1105, PG. 146			HEIMVIAMININI
		, and an	7.11.5 2. 7.00, 7 3. 740	MAR 1.7 1999
				SECTION
3.	Description of corner evidence found and/or method applied in restoring or reestablishing corner:			
	FOUND PK NAIL OVER R.R. SPIKE W/LARGE PK NAIL NEXT TO SPIKE LOCATION AGREES WITH LCRC'S AND RECORDED SURVEY'S			
				`
	ACCEPTED AS THE B	SEST AVAILABLE EVIDENCE	OF THE LOCATION OF THE ORIGIN	IAL CORNER
) ,	Description of monument for corner and accessories established to perpetuate locating the position of the corner:			
	SET 5/8" RE-BAR W / BAY COUNTY REMON. BRASS CAP & NO. 26454 IN MONUMENT BOX			
	S40°E 48.00′ NAIL & TAG #18064 IN NE FCE TELE BOX STUD POLE - 48.02′ REC			
	S70°W 34,85° FCE STOP SIGN POST			
	N36°W 72.53′ NAIL & TAG #9433 IN NE FCE PWR POLE - 72.5′ REC			LAND SURVEYOR
	S65°W 40.09′ FCE ROA	AD SIGN POST	APPROVED LAI	NO. 26454
	A. 345 OF 1990			90 - Bay County A Color
		III	MJN	Y ONAL SUR
igne	d by Sucen.	1) terda	Michael MacDor Gayerty Represel	nald P.S. Mative December 23, 1998
urve	yor's Michigan License N	lo. 26454		December 23, 1990
				