LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF—:	LOCATED IN—:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 25 N., R. 13 W.	G-3;
2. PROPERTY CONTROLLING IN SECTION 4	T. 25 N., R. 13 W.	2; 9
3. MISCELLANEOUS PROPERTY IN SECTION 4	T. 25 N., R. 13 W.	657'-W of G-2

4. LOT NO. _____, RECORDED PLAT _____

5. PRIVATE CLAIMS _____

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Carl F. Roser, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on November 18, 1980, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on Nov. 18, 1980, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

C. Continued:

9

Drove 5/8"x3' re-rod w/RLS cap & set Cedar post w/loc tag

8"	Cedar	S55°W	18.7
4"	Cedar	S40°E	6.5
14"	Maple	N70°E	34.5'

657'-W of G-2

Drove 5/8"x36" re-rod w/RLS cap & Set Ced. Post w/loc tag

5"	Maple	S19°W	26.8'
9"	Maple	N27°W	60.5'
2"	Maple	S53°E	36.4'

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

G-3 Found & accepted 1/2" re-rod for SE Cor. of Sec.4. Cor is in remains of old Cor. Fn. post bottom with fn. running S. & W.

2 Set E 1/8 on North line of Sec.4 Midway & on line btw. NE & N 1/4 Cor's of Sec. 4.

9 Established SE corner of W 1/2 of Frl. NE 1/4 of Sec. 4. per std. B.L.M. instructions.

657'-W

G-2 Established SW Cor. of E 1/2 of E 1/2 of frl. NE 1/4 of Sec.4 per std B.L.M. Instructions.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

G-3

Fd 1/2" re-rod replaced w/DNR Mon & set Cedar post

8"	Maple	S13°W	6.3'
12"	Maple	N32°W	22.2'
6"	Maple	N69°E	36.5'

2

Drove 5/8"x36" re-rod w/RLS cap & Set Ced. Post w/loc tag

10"	Maple	N32°E	29.1'
8"	Maple	S50°E	12.2'
6"	Maple	N61°W	10.0'

SIGNED BY Carl F. Roser 3-31-81 DATE _____

STATE OF MICHIGAN — CARL F. ROSER — LAND SURVEYOR — (SEAL) — 12028 — REGISTERED LAND SURVEYOR

SURVEYOR'S MICHIGAN REGISTRATION NO. 12028

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ (CHIEF OF SURVEY PARTY) DATE _____

APPROVED AND SIGNED BY _____ (MICHIGAN REGISTERED LAND SURVEYOR) DATE _____

(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

Colfax Township
BENZIE COUNTY

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
REVISED MAY 14, 1975

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET