LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF—:	LOCATED IN—:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 25 N., R. 13 W.	K-10; J-9; I-10
2. PROPERTY CONTROLLING IN SECTION	,T. N. S., R. E. W.	
3. MISCELLANEOUS PROPERTY IN SECTION	,T. N. S., R. E. W.	

4. LOT NO. _____ , RECORDED PLAT _____

5. PRIVATE CLAIMS _____

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Carl F. Roser, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on November 21, 19 80, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

C. Continued:

I-10
Fd 1 1/4" pipe
3" Cherry S14°W 74.2
7" Cherry S78°E 17.7
Set Loc Tag on Cor. King Post

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

K-10 Accepted Fd 1" pipe for E 1/4 Cor.Sec.26, Langford notes at Benzie Co.Courthouse indicate he set 1" pipe here; see Liber "O", Pg. 134.

J-9 Accepted Fd Gas Pipe for N 1/4 Cor. Sec.26. Langford notes at Benzie Co. Courthouse note he set 1" gas pipe; See Liber "O", Pg. 134.

I-10 Fd & accepted 1 1/4" pipe at Cor. Fence post, fn N-S-W. Pettett, 1900+, S-26, calls for Gas Pipe, see Liber "O", Pg. 134.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

K-10
Fd 1" pipe,added ced.post w/loc tag
8" Maple N32°E 4.55
8" Twin Maple N73°W 18.50
8" Maple S07°E 33.75
E-W fn.wire in trees South 90'(±10')

J-9
Fd. Gas Pipe & added Ced. Post w/loc Tag
12" Cedar N65°W 13.4
10" Cedar S18°W 38.0
5" Hemlock N73°E 32.8

SIGNED BY Carl F. Roser 3-31-81 DATE _____

STATE OF MICHIGAN CARL F. ROSER LAND SURVEYOR No. 12028 (SEAL) REGISTERED LAND SURVEYOR

SURVEYOR'S MICHIGAN REGISTRATION NO. 12028

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____
MICHIGAN REGISTERED LAND SURVEYOR

(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

Colfax Township
BENZIE COUNTY

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
REVISED MAY 14, 1975

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET