LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF –:	LOCATED IN –:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY_____ T. 25 N., R. 13 W.		F-5; E-4; E-5
2. PROPERTY CONTROLL-ING IN SECTION 9 , T. 25 N., R. 13 W.		3
3. MISCELLANEOUS PROPERTY IN SECTION_____ , T._____ S., R._____ W.		
4. LOT NO._____ , RECORDED PLAT_____		
5. PRIVATE CLAIMS_____		

REGISTER OF DEEDS STAMP AND _____ FILING NUMBER

I, ____Carl F. Roser____ , do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on____November 19,____, 19_80_, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on_____ , 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX XXX XXXXXXXXXX XXXXXX XXXXXXXXX XXXXXXXXX

C. Continued: 3   E-5

Rd Re-rod w/RLS cap #10681			Fd 3/4" Rod		
*12" Maple	N35°W	25.90	*10" Scotch Pine	S37°E	74.32
*36" Beech	S30°W	62.35	P. Pole	S48°W	45.87
*Re-rod w/RLS Cap #10681	W	32.91	Ctr. N-S gr. rd.	E	3'±
*Fd 1 1/2" pipe	W	32.27	Ctr. E-W B.top rd.	S	2'±
Set Ced.Post W/loc Tag	W	33'	Set Ced.Post w/loc Tag	N45°E	47.5

   *Old Wits.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

F-5: Fd & accepted 3/4" pipe for S 1/4 Cor. of Sec.9. (Fd stone dip S83 1/2°E, 34'; did not dig out, believe to be old un-recorded plat cor.) The fd. pipe fits 1890 Chicago & West Mich. R.R. tie North of 517' & West 360'.

E-4 Accepted Fd 5/8" re-rod for W 1/4 Cor. Sec.9. Cor fits two RLS, H.Bruning Wits.

3 Fd re-rod as set by RLS, H. Bruning, #10681. Ctr. of N-S gravel rd is E. 4'±.

E-5 Fd & accepted 3/4" rod for SW Cor. Sec.9. Cor fits two RLS, H. Bruning and one Benzie Co. Rd. Com. Wits.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

        F-5   E-4

Fd 3/4" pipe 1'± deep			Fd 5/8" Re-Rod (buried 0.5)		
Raised w/1"x12" pipe w/RLS cap			*20" Cedar	N23°W	34.17
P. Pole	S58°E	63.00	16" Maple (Triple)	S60°W	31.61
28" Maple	S75°W	81.21	*13" Maple	S79°E	28.72
Set Ced.Post w/loc Tag	N	33'	Fd Re-rod w/RLS Cap 10681	W	33.00
Ctr. E-W Blk T. Rd.	S	1.5'	Ctr. N-S Gr. Rd.	E	1'
			Set Ced.Post w/loc Tag	W	33'

* Old Wits.

SIGNED BY__ *Carl F. Roser* __ 3-31-81 __ DATE

SURVEYOR'S MICHIGAN REGISTRATION NO.__12028__

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY_____ DATE_____
             CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY_____ DATE_____
             MICHIGAN REGISTERED LAND SURVEYOR

(SEAL)

(Seal: STATE OF MICHIGAN — CARL F. ROSER LAND SURVEYOR No. 12028 — REGISTERED LAND SURVEYOR)

Colfax Township
BENZIE COUNTY

SURVEYOR'S MICHIGAN REGISTRATION NO._____

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET