LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF—:	LOCATED IN—:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 25 N., R. 14 W.	D-4; G-5
2. PROPERTY CONTROLLING IN SECTION 8	,T. 25 N., R. 14 W.	5; 12
3. MISCELLANEOUS PROPERTY IN SECTION	,T. N. S., R. E. W.	

4. LOT NO. _____ , RECORDED PLAT _____

5. PRIVATE CLAIMS _____

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Carl F. Roser, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on Jan. 12, 1979, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19___, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

C. continued

12

Drove 5/8"X40" re-rod
& Ced. Post w/Loc. Tag.

6" R.Pine	S25°W	35.5
5" R.Pine	N67°W	32.0
32" Cherry	S87°E	68.8

Fd. 1 1/2" Pipe N01°52'W 24.29
Ctr. narrow N-S dirt trail rd.
Due E 46'±

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

D-4 Fd. and accepted Bed Rail for Ctr. of Sec. 8. Fits fd. Ir's. N. 1/4 mile per "Plat of Orchardville No.4". Straight line E-W 1/4 line would be 7'± So.

G-5 Found & accepted Benzie County Mon. for SE Cor. Sec. 9, in approx. Ctr. of N-S B.Top Co. Rd. & in line with trail road to west.

5 Fd. & accepted 1" pipe for 1/8 Corner; fits "Plat of Orchardville No.2", Plat of Orchardville No.3" and "Plat of Orchardville No.4".

12 Established 1/8 Cor. eqidistant & on line between ctr. Sec. N. & 1/4 Cor. S.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

D-4

Fd. Bed Rail. Replaced with 5/8"X40" re-rod w/RLS Cap & Ced. Post w/Loc. Tag.

10" Cherry cluster of 4	N53°E	59.2
12" Cherry	N74°W	42.6
5" Tw.Maple	S40°E	33.0
N-S trail rd.	Due E	86'±

G-5

Fd. Benzie Co. Mont.

6" R.Pine	N83°E	49.79
6" W.Pine	S62°E	53.32
6" W.Pine	N46°W	59.83

5

Fd. 1" pipe & Set Ced. Post w/Loc. Tag.

7" Apple Tree	S40°E	77.8
4" W.Pine	S56°W	16.5
8" Cherry	N68°E	59.1

Ctr. Narrow N-S dirt rd.
Due E. 31'±

SIGNED BY Carl F. Roser 2-12-79 DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO. 12028

(SEAL)

STATE OF MICHIGAN
CARL F. ROSER
LAND SURVEYOR
No. 12028
REGISTERED LAND SURVEYOR

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____
MICHIGAN REGISTERED LAND SURVEYOR

(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

WELDON TOWNSHIP
BENZIE COUNTY

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
REVISED MAY 14, 1975

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET