LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF—:	LOCATED IN—:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 25 N. ●., R. 14 ● W.	D-5; E-4; E-5
2. PROPERTY CONTROLLING IN SECTION 8	,T. 25 N. ●., R. 14 ● W.	7; 14
3. MISCELLANEOUS PROPERTY IN SECTION	,T. N. S., R. E. W.	

4. LOT NO. _____ , RECORDED PLAT _____

5. PRIVATE CLAIMS _____

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Carl F. Roser, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on June 15, 19 78, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

C. continued

7			14		
Fd. 1" pipe & Set Ced.Post w/Loc. Tag			Drove 5/8"X40" re-rod w/RLS Cap & Ced. Post w/Loc. Tag.		
5" W.Pine	N23°W	12.1	7" Maple	N10°E	19.3
5" W.Pine	S85°W	14.2	6" Tw.Maple	N66°W	11.6
5" Ir.Wood (cluster)			5" Maple	S24°E	11.1
Due S	27.4				

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

D-5 Fd. and accepted 1" pipe for 1/4 Cor. Corner is in line with old field edge berm (fence all down) to west.

E-4 Fd. and accepted 1" pipe for 1/4 Corner. Fits 1/8 Cor. & Sec. Corner N. and Sec. Corner S. very close.

E-5 Fd. & accepted 1" pipe for Sec. Corner. Fits 1/4 Cor's. & Sec. Cor's. to N.,S. &W. very reasonable.

7 Fd. & accepted 1" pipe for 1/8 Corner; SE Corner of "Plat of Homestead Orchard No. 3". Sand trail road cross Sec. Line 30'± north of corner.

14 Estab. 1/8 Cor. equidistant & on line between 1/4 Cor. N. & Sec. Cor. S.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

D-5			E-4			E-5		
Fd. 1" Pipe (bent), replaced with DNR Mon.(buried 0.5')			Fd. 1" pipe & replaced w/DNR Mon. & Ced. Post			Fd. 1" Pipe. Replaced w/DNR Mon. & Ced. Post.		
25" Cherry	S31°E	71.7	5" Maple	N25°W	16.3	9" Cherry	N14°W	24.1
24" Maple	S20°W	60.6	6" Cherry	N28°E	9.2	15" Cherry	S65°W	26.2
20" Cherry	Due N	119.7	6" Maple Cluster	S38°W	8.5	7" W.Pine	S51°E	64.4
Set Ced.Post w/Loc.Tag.			N-S Rand	Due W.	2'±			
	Due W	33'						
Ctr. narrow N-S dirt trail rd.								
	Due E	6'±						

SIGNED BY Carl F. Roser 2-12-79 DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO. 12028

STATE OF MICHIGAN CARL F. ROSER LAND SURVEYOR No. 12028 REGISTERED LAND SURVEYOR

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____
MICHIGAN REGISTERED LAND SURVEYOR

(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

WELDON TOWNSHIP
BENZIE COUNTY

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
REVISED MAY 14, 1975

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET