LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF—:	LOCATED IN—:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 25 N. S., R. 14 E. W.	A-1
2. PROPERTY CONTROLLING IN SECTION 5	,T. 25 N. S., R. 14 E. W.	5; 12
3. MISCELLANEOUS PROPERTY IN SECTION	,T. N. S., R. E. W.	

4. LOT NO. _____ , RECORDED PLAT _____

5. PRIVATE CLAIMS _____

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Carl F. Roser, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on Jan. 10, 19 79, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

B. continued

12 Fd. & accepted 3/4" pipe for 1/8 corner; corner common to "Plat of Orchardville", "Plat of Orchardville No. 1" and "Assessors Plat of Cherry Grove".

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

A-1 Fd. Benzie Co. Mon. (buried) 1"+ N. of ctr. of E-W gravel rd. Corner Comm. to T25&26N-R14&15W. Crooked trail to south is 10'+E.

5 Fd. 3/4" pipe (buried) near E'ly edge of narrow N-S gravel road, said pipe fitting C.P. Tuller's survey & Sec. Sub'n. of Sec. 5 (SE Cor. of NE frl. 1/4 of NW frl. 1/4) dated May 1900, which fits the original Govt. Survey -GLO Plat- pro-rated. There is evidence of real old B-W fence to west on ground. The south line of "Assessors Plat", record, would be 26'+ south, there being no evidence on the ground of any monumentation for several hundred feet west.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

A-1			5			12		
Fd. Benzie Co. Mon.			Fd. 3/4" pipe,buried (0.4')in rd.			Fd. 3/4" pipe (buried) in N-S		
3" Cherry	S39°E	56.52	8" Maple	N68°W	31.2'	sand trail rd. (buried 0.3)		
5" R.Pine	S58°E	114.40	9" Cherry	S64°W	30.6'	26" Cherry	N57°E	26.9'
3" Cherry	S07°W	67.00	4" Tw.Ironwood	N69°E	35.3'	21" Cherry	S49°E	27.4
Set Ced.Post w/Loc. Tag			Ctr N-S Dirt Rd. Due W		3'+	8" R.Pine	N60°W	42.6'
	Due N	33'	Set Ced.Post w/Loc. Tag			Ctr. N-S sand trail rd.		
Fd. re-rod				Due W	33'		Due W	1'+
W/RLS Cap	Due N	33.00'				Set Ced.Post w/Loc. Tag		
							Due W	16.5

SIGNED BY Carl F. Roser 2-12-79 DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO. 12028

STATE OF MICHIGAN CARL F. ROSER LAND SURVEYOR No. 12028 REGISTERED LAND SURVEYOR

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____
MICHIGAN REGISTERED LAND SURVEYOR

(SEAL)

WELDON TOWNSHIP
BENZIE COUNTY

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
REVISED MAY 14, 1975

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET