## LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

	FOR CORNERS OF -:	LOCATED IN -:	CORNER CODE NUMBER	1	
	1. PUBLIC LAND SURVEY	T. 25 N. R. 14 W.	D-1		
	2. PROPERTY CONTROLL: 4 ING IN SECTION——	,T. 25 N. R. 14 W.	15		
	3, MISCELLANEOUS PROPERTY IN SECTION	,T N. R E. W.			
	4. LOT NO, RECORDED PLAT				
	5. PRIVATE CLAIMS			REGISTER OF DEEDS STAMP AND FILING NUMBER	
	I,, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines I and 2 above were, in a field survey on June 15,1978				
	the corner points mentioned in lines I and 2 above were, in a field survey on June 15, 1978, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on				
	XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX				
15	Fd. & accepted 1" pipe for 1/8 Corner; corner common to "Homestead Orchard" and "Plat of Homestead Orchard No. 1".				
D-1	<ul> <li>B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:</li> <li>D-1 Restored N 1/4 Cor., Sec. 5, on Twp. Line per F. Haswell Survey, June 1909, of So. Line Sec's. 32 &amp; 33, T26N-R14W and on line across fd. 1/8 Cor. &amp; Ctr. of Sec. 5 to So. &amp; fd. Ir. 3.56'-N. per C.P. Tuller Survey of Sec. 5 in May 1900. Tuller set N 1/4 Cor. Sec. 5 by compass due E. of std. cor. (S 1/4 Sec. 32); therefore fd. Ir. 3.56'-N. was accepted only to control the direction of the N-S 1/4 line of S-5. The recorded plat "Assessors Sub'n. of NE fr1.1/4-NW fr1. 1/4 of Sec. 5" by James Pettitt, 1927, does not fit Tullers sub'n. of Sec.5, by 26 ft. + N&amp;S, nor was Pettitt's plat monumented or occupied very much, if at all; said "Assessors plat" was therefore ignored as control for Twp. Line or Sec. 5 Subdivision.</li> <li>C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:</li> <li>D-1</li> </ul>				
Set	DNR Mon. & Ced. Post.		Fd. 1" pipe & Set (	Ced. Post W/Loc. Tag.	
24" 6"	Maple         S38°W         84.6           Maple         N25°W         38.1           Maple         N18°E         17.8	8 2	13" Triple Cherry	N63°W 16.9 S11°W 25.6	
12"	Maple N18°E 17.8	3	8" W.Pine 11" W.Pine	N45°E 37.8	
Fd.	5/8" Ir. S83°54'W 8.5		Ctr. E-W Trail Rd.	Due N. 50'+	
S 1/	E-W dirt Co. Rd  Due S. 13' '4 Cor. S-32(26-14)	_		WE OF MICKING	
	N89°40'W 300.	07'	7 /	CARL	
	SIGNED BY	lail +	Kell DATE 2-12	79 F. ROSER X	
SIGNED BY  SIGNED BY  CARL F. ROSER LAND SURVEYOR'S MICHIGAN REGISTRATION NO. 12028  FOR STATE AND UNITED STATES AGENCIES:					
				TARIL LARIES	
	SIGNED BY	HIEF OF SURVEY PARTY	DATE		
SIGNED BY DATE CHIEF OF SURVEY PARTY  APPROVED AND SIGNED BY DATE MICHIGAN REGISTERED LAND SURVEYOR					
MICHIGAN REGISTERED LAND SURVEYOR (SEAL)					
!	SURVEYOR'S MICHIGAN REGIS	TRATION NO		LDON TOWNSHIP NZIE COUNTY	