BLAINE TOWNSHIP		OCORNER RECORDATION Requirement of Act 74, I		· · · · · · · · · · · · · · · · · · ·	
For corners in	L1971	ig Requirement of Act 14, i	VIICII. F.A. 191	STATE OF MICHIGAN	
BENZIE COUNTY (County)	Located in:	Corner Code #		BENZIE COUNTY RECORDED	
1. Public Land Survey	T <sup>25N</sup> R <sup>1</sup> TR TR TR			22 JAN 1999 3:02:00 PM MICHELLE R. GRAY REGISTER OF DEEDS # PAGES	
Property Controlling     in Section     Miscellaneous     Property in Sec.	S TR S TR S TR			Register of Deeds Stamp & File Num	ber
A Lot No. Dogor	ded Plat				
5. Private Claims				A B C D E F G H I J K	L 1
				2 6 5 4 3 2 3	-1-
requirements of P.A. 74, Michiga conformance with regulations and United States Department of the I that the corner points mentioned	in P.A. of 1970, the come rules therefore as require nterior, Bureau of Land M in lines 3, 4 and 5 above a Decree of a Court of	12/4 , 19 98 do hereby er points mentioned in lines 1 and 2 do in the current manual of survey in lanagement or by a decree of a Coul were in conformance with the rules of Law; established, re-established	2 above were in structions of the rt of Law and /or of the Michigan	4 7 8 9 10 11 5 6 15 14 7 8 19 20 21 22 23	-121324
NOTE: Not more than 2 corr on this certificate.	ers, all in the same tow	n and range, may be recorded		9 29 28 27 26	-25
				11	-36
A. Description of original mo	nument and accessori	ies and/or subsequent restoration	on:	13	L
Page 128, shows he set ced 1/16 corner to Northof 1/4 1962: MDOT found 1" iro	ar post by old bearing corner, midway betwo n pipe, 12" below exi ards, in work for the	g trees. He did this work in a een this corner and section co isting grade and witnessed it.	break of the Ea rner to north. I MDOT plans s	1882: Sam Davidson, Survey Record I, st 1/2 of the NE 1/4 of section 34. He set Davidson distance to north was 2647.92'. show the corner 14.74' south of centerlines found 1" iron pipe. The distance to the	3
B. Description of corner evid	dence found and/or mo	ethod applied in restoring or ree	establishing corn	er:	
Because of large difference 1/16 corner set by Davidson pipe. A double of this dista	in distances between n at a MOL position. ance is within 5 feet of	Davidson and Richards, we a We measured to the North at of total distance measured by l	measured to second found the real Richards. The	the North and fitting MDOT witnesses. tion corner to the South and also North to mains of an old fence, 1357' North of iror distance to the South was measured at petuation of the original GLO corner from	n
C Description of monument	for corner and access	ories established to perpetuate	locating the nos	ition of the corner	
		- · ·	umentation Pro	gram concrete monument with a brass ca	p
MDOT right of w MDOT right of w 17" Twin Maple	ay monument South ay monument North S52°W 70.88' to set	64.76'.	•	Ratified by Peer Group In accordance with P.A. 345 Chairman Date 11 24198	
Signed by	3. S. J.	Q	Date	1/22/99	
Surveyor's Michigan License	No. <u>//</u> ?	30895			