

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD


BENZIE COUNTY
T 26 N R 13 W

DESCRIPTION OF CORNER N W Corner, Section 7

CORNER MONUMENT Found Wagon Skain, Added DNR Men. & Cedar post

DATE MONUMENT PLACED AND WITNESSED 4-24-72

WITNESSES TO CORNER..... 5" Maple S 1 W 53.2'



8" B. Cherry N 22 W 55.9'


9" B. Cherry N 43 E 38.3'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Found old wagon skain (axle) in old fence remains N-S-E. Fits 1/8 corner & 1/4 corner to North.



DISTRIBUTION:

SIGNED

Carl F. Roser

DATE

5-23-72

REGISTERED LAND SURVEYOR **12028**

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing