

STATE OF MICHIGAN  
DEPARTMENT  
OF  
NATURAL RESOURCES

LAND CORNER RECORD


BENZIE COUNTY  
T 26 N R 13 W

DESCRIPTION OF CORNER S 1/4 corner Sec. 7

CORNER MONUMENT Set DNR Monument & Cedar Guard Post

DATE MONUMENT PLACED AND WITNESSED 4-24-72

WITNESSES TO CORNER..... 8" Maple S 18 W 23.5'



16" B. Cherry N 23 E 42.0'

7" Maple N 82 E 34.8'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

**Corner reestablished single proportion to U.S. between recovered Section Corners to E & W. Corner fence post (Fence W & Irregular S) Approx. 20' S & 14'E.**



SIGNED

*Carl F. Roser*

DATE

5-23-72

REGISTERED LAND SURVEYOR **12028**

DISTRIBUTION:

County Courthouse  
Area Forester (Regions I & II)  
District or Region Surveyor  
Forestry Div., Lansing

R 4047  
Rev. 10/68