LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF—:	LOCATED IN—:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 26 N. ●., R. 13 ●. W.	C-7; C-8
2. PROPERTY CONTROLLING IN SECTION 20	,T. 26 N. ●., R. 13 ●. W.	10
3. MISCELLANEOUS PROPERTY IN SECTION	,T. N. S., R. E. W.	

4. LOT NO. , RECORDED PLAT

5. PRIVATE CLAIMS

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Carl F. Roser, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on November 17, 19 80, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on , 19 , found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

C. Continued;

10

Fd 1" Pipe (buried 0.3)

11" Oak (Triple)	N65°E	136.0
9" Cherry(Clump)	S23°E	118.6
Set Cedar Post w/loc tag	E	16.5'
Ctr. N-S Tr. Rd.	W	4'±

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

C-7 Fd. old sq. Conc. Mon. (hit on top) that fits BT's by R.L.S., H.R. Bruning.

C-8 Recovered 1" pipe in poured conc. for E 1/4 corner of Sec.19 per 1927 recorded plat of "Turtle Lake Resort".

10 Recovered 1" pipe for south 1/8 corner on E. line of Sec.19 per 1927 recorded plat of "Turtle Lake Resort".

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

C-7

Fd. 7"x7"x 2.5' sq. Reinforced Conc.
Added DNR Mon.(flush w/grd.) & cedar post

8" Maple	N15°W	61.2
14" Maple	N37°W	66.6
*14" Elm (stump)	N52°E	25'
* 9" Elm (stump)	S71°E	70.9'
*14" Maple	N37°W	66.6'

C-8

Fd 1" pipe in conc. (buried 0.3)

7" Maple (twin)	N77°W	48.1
6" Maple	N35°W	39.0
13" Maple (triple)	S21°W	102.3
Set Ced. Post w/loc tag	E	16.5
Ctr. N-S Tr. Rd.	W	2'±

*Old H.R.B. Wits

SIGNED BY Carl F. Roser 2/20/81 DATE

STATE OF MICHIGAN CARL F. ROSER LAND SURVEYOR No. 12028 REGISTERED LAND SURVEYOR (SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. 12028

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY DATE
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY DATE
MICHIGAN REGISTERED LAND SURVEYOR

(SEAL)

Inland Township
BENZIE COUNTY

SURVEYOR'S MICHIGAN REGISTRATION NO.

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
REVISED MAY 14, 1975

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET