# LAND CORNER RECORDATION CERTIFICATE

## FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

| FOR CORNERS OF—: | LOCATED IN—: | CORNER CODE NUMBER |
|---|---|---|
| 1. PUBLIC LAND SURVEY | T. ___ N. S., R. ___ E. W. | |
| 2. PROPERTY CONTROLLING IN SECTION 29 | T. 26 N. S., R. 13 E. W. | 11; 16 |
| 3. MISCELLANEOUS PROPERTY IN SECTION ___ | T. ___ N. S., R. ___ E. W. | |

4. LOT NO. ___, RECORDED PLAT ___

5. PRIVATE CLAIMS ___

REGISTER OF DEEDS STAMP AND FILING NUMBER ___

I, Carl F. Roser, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on July 28, 1980, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on ___, 19___, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

xxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxx

C. Continued: 16 cont.

Ref. Cor. - Set 5/8"x36" re-rod
w/RLS Cap & Ced.Post with Loc. Tag.

| | | |
|---|---|---|
| 1/8 Corner (in lk.) | S89°18'W | 43.46 |
| 6" Ced. | N68°W | 15.56 |
| 4" R. Pine | S10°W | 6.82 |
| Fd Sq. Conc. Mon | N37°36"W | 3.00 |

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

11 Recovered ctr. of SW 1/4 of Sec. 29, old 1"x18" pipe, per 1927 plat of "Turtle Lake Resort".

16 Restored E 1/8 Corner on South line Sec.29 (Comp Point in Lake - nothing set, see ref. Cor's item "C") equidistant & on line between S 1/4 Cor. & SE Cor. of Sec. 29.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

11

| | | |
|---|---|---|
| Fd 1"x18" Pipe | | |
| 4" Maple | N28°E | 29.7 |
| 4" Maple | N30°W | 32.1 |
| 8" Oak (twin) | S18°E | 36.0 |
| Set Ced. Post w/loc tag | N | 16.5' |
| Ctr. E-W Sand Trail | S | 2'± |

16

1/8 Cor. falls in Turtle Lake, Nothing set.
Ref.Cor - Set 5/8"x36" re-rod w/RLS cap & Ced Post with loc. tag.

| | | |
|---|---|---|
| 1/8 Corner (in lk.) | S00°30'E | 55.00 |
| 7" W. Oak | N35°W | 16.42 |
| 5" R. Oak | N60°E | 6.71 |

SIGNED BY Carl F. Roser 2/20/81 DATE ___

STATE OF MICHIGAN — CARL F. ROSER LAND SURVEYOR No. 12028 — REGISTERED LAND SURVEYOR

SURVEYOR'S MICHIGAN REGISTRATION NO. 12028

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY ___ DATE ___
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY ___ DATE ___
MICHIGAN REGISTERED LAND SURVEYOR

(SEAL)

INLAND TOWNSHIP
BENZIE COUNTY

SURVEYOR'S MICHIGAN REGISTRATION NO. ___

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
REVISED MAY 14, 1975

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET