LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF—:	LOCATED IN—:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 26N N., R. 13W W.	E-3, E-4
2. PROPERTY CONTROLLING IN SECTION 8	T. 26N N., R. 13W W.	8, 9
3. MISCELLANEOUS PROPERTY IN SECTION	T. N. S., R. E. W.	

4. LOT NO. _____, RECORDED PLAT _____

5. PRIVATE CLAIMS _____

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, CARL F. ROSER, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on 6/15, 1982, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

C, CONT.

~~A. Description of corner evidence found and/or method applied in restoring or re-establishing corner:~~

9

DROVE 5/8"X36" RE-ROD W/RLS CAP & SET CED POST W/LOC TAG.

20" TWIN MAPLE	S40°E	14.7'
10" MAPLE	S10°E	30.0'
12" MAPLE	S50°W	30.3'
5" MAPLE	N84°W	1.6'

(B. CONT.)

9 (CONT.) FENCE POST (FN REMAINS SOUTH) N60°E, 1.8' FROM RE-ESTAB 1/8 COR. COR FALLS NEAR NW COR OF OLD SMALL OVER-GROWN CLEARING. TOP EDGE OF RAVINE DOWN TO STANLEY CREEK IS NORTH 40'±.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

E-4 FD 1" PIPE (BURIED 0.4') IN WESTERLY WHEEL TRACK OF OLD N-S TWP RD GRADE. FITS D.F.HOLDIN 1876 SURVEY OF SEC. 8; SEE CO. SURVEYORS RECORD, PGS 112-113 AT REG. OF DEEDS.

E-3 FD 1 1/4" PIPE (BURIED 0.3') 2'± NORTH OF CTR OF E-W GRAVEL RD AND IN LINE WITH CTR OF TWO TRACK TO SOUTH. COR IS IN LINE WITH OLD FENCE TO NORTH, MOSTLY DOWN.

8 RE-ESTAB NW COR OF NE 1/4 - SW 1/4 OF SEC. 8 MID-WAY & ON LINE BETW RECOVERED CTR & W 1/4 COR'S OF SEC. 8. VERY IRREGULAR FENCE INTERSEC (FN'S E-W-N) IS ABOUT 50'± NORTH.

9 RE-ESTAB NE COR OF NW 1/4-SE 1/4 OF SEC 8 MID-WAY & ON LINE BETW RECOVERED CTR & E 1/4 COR'S OF SEC. 8. FD OLD RUSTY-SPLIT 1/2" PIPE STUCK IN GROUND BY REMAINS OF ROTTED-OFF

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

E-3

FD 1 1/4" PIPE (BURIED 0.3).

* 4" SCRUB ASH	N30°E	27.27
*6" J. PINE	S35°E	55.95
*5" J. PINE	S70°W	101.95
CTR OF 14" C.M.P.	WEST	44°±
SET CED POST W/LOC TAG	NORTH	33'

E-4

FD 1" PIPE (BURIED 0.4)

*12" MAPLE	S09°W	50.80
*10" MAPLE	N45°W	20.94
*14" MAPLE	N33°E	46.72
*24" W. PINE	S42°E	39.50
CTR 12' CREEK C-WLY (STANLEY)	SOUTH	190'±
SET CED POST W/LOC TAG.	WEST	33'

8

DROVE 5/8"X36" REROD W/RLS CAP & SET CED POST W/LOC TAG

6" MAPLE	N20°W	16.1
20" HEMLOCK	S66°E	72.4'
5" MAPLE	S78°W	28.9

* OLD WITS

SIGNED BY Carl F. Roser 6-24-82 DATE _____

STATE OF MICHIGAN — CARL F. ROSER LAND SURVEYOR No. 12028 — REGISTERED LAND SURVEYOR

SURVEYOR'S MICHIGAN REGISTRATION NO. 12028

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____
MICHIGAN REGISTERED LAND SURVEYOR

(SEAL)

INLAND TOWNSHIP
BENZIE COUNTY

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
REVISED MAY 14, 1975

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET