LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Located In: Corner Code #

For corners in

Benzie (County)

1. Public Land Survey	T 26N R 13W	E-2	Register of Deeds Stamp & File Numb
,	TR		
2. Property Controlling	STR		
in Section 3. Miscellaneous	S T R S T R		A B C D E F G H I J K I, M
Property in Sec.	S T R		2 6 5 - 6 - 4 3 - 2 1
			3
			4 - 7 - 12
I Crain W McVean in	a field survey on	98 do	5
	nents of P.A. 74, Michigan P.A. of 19		6 18 17 16 15 14 13
-	1 and 2 above were in conformance to s required in the current manual of sur		7
instructions of the United States	Department of the interior, Bureau of	Land	8 192021 22 23 24
	Court of Law and /or that the corner ove were in conformance with the rul		10-30 29 28 27 26 25
Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:			
re-established, monumented, rec	overed, round as expressed below:		123132 33 343536
			13
NOTE: Not more than 2 of this certificate.	corners, all in the same town an	d range, may be recorded on	
	nonument and accessories and/or	r subsequent restoration:	
E-2 - GLO - Set ¼ post Alv	vin & Austin Burt - 1839	- C.P.Tulle	er - Bk. 1, P 2&3 -Sec. 5 Survey Notes - 1899
Sugar 9" West			ND. good post and both witnesses
Sugar 7″ S88°l - C.P. Tuller – 1898 – 9			Gourdie, Miller, Batzer – NGMB Notes – 1966 Set Iron
Sugar 6" N32°	•		NW 19.90′ 10″ Maple
Sugar 13" S88	°30′W 17′		NE 6" Maple 42.08"
			E 15" Basswood 59.95'
B. Description of corner ev	ridence found and/or method app	olied in restoring or reestablish	ning corner:
w/ fence post guard p that the overall distant to the S. bank of the F survey in Sec. 5 by mo At the ¾" Pipe, 2 stra & a field line bears N8 apparent on 1938 aeri The Sugar Maple trees physical evidence of T the SW1/4 of Sec. 5, Accept FND. ¾" Iron I	er NGMB notes, within 2' ± of Soce between E-3 & E-1 is 5375.6 Platte River is 3650' – GLO; vs. anumentation and occupation called sof barbed wire on ground & 5°E. An old N-S field line w/ trail photos. An extensive search in this area are 16" ±, or smalled fuller's position found. Due to intextending the E-W ¼ line from CPipe as the best available eviden	P position between E-1 & E-3 ', measured, vs. – 5510' GLO 3742'± 10', measured – an o culates 98.4' North of the ¾' in trees; meanders N to the rices of fence is 80'± 20' to th was made for evidence of Tuler and not considered to be of consistencies between Tuller' C-2 thru D-2, to the east, is arce of the position of the origin	
C. Description of monument	for corner and accessories estal	blished to perpetuate locating	the position of the corner:
E-2 - Replaced %" x 1.9' lor	ng Iron Pipe w/ Benzie Co. Conci	rete Monument	
	N&T in NE. Side 14" S. Maple (N nail in W. Side 17" S. Maple	IGMB)	OF MICH.
	&T in E. Side 7" S. Maple		C. C.
	N&T in S. Side 13" S. Maple		CRAIG W.
	N&T in NW. Side 11″ S. Maple (I N&T in N. Side 24″ Basswood (N		MCVEAN (E
	st 1' NE. Reset steel fence post		SURVEYOR
FFAIR and above a los	· •		39098 No.
*FND. nail above or be	low		OPESSIONAL
Q. M	i Me Ai		. / /
Signed by Crang M			Date 10/6/1998
Surveyor's Michigan License	No3	9088	
FORM APPROVED BY MICHIGAN STATE BOARD OF PROSESSIONAL SURVEYORS, LAN. 28, 4011			

Register of Deeds Stamp & File Numb,