

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

| | | | |
|--|---------------------------------------|---------------|-------------|
| For Corners In: <u>Benzie</u> (County) | Located In | Corner Code # | |
| 1. Public Land Survey | T _____ R _____ | | |
| | T _____ R _____ | | |
| 2. Property Controlling in Section | S <u>16</u> T <u>26N</u> R <u>13W</u> | | <u>9</u> |
| | S _____ T _____ R _____ | | |
| 3. Miscellaneous Property in Section | S <u>16</u> T <u>26N</u> R <u>13W</u> | | <u>CWE</u> |
| | S _____ T _____ R _____ | | <u>1/64</u> |

Register of Deeds Stamp & File Number

4. Lot No: _____ Recorded Plat: _____

5. Private Claims: _____

I, Craig W. McVean, in a field survey on Feb. 12, 1998 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

| | | | | | | | | | | | | | |
|----|----|---|----|---|----|---|----|---|----|---|----|---|---|
| | A | B | C | D | E | F | G | H | I | J | K | L | M |
| 1 | | | | | | | | | | | | | |
| 2 | 6 | | 5 | | 4 | | 3 | | 2 | | 1 | | |
| 3 | | | | | | | | | | | | | |
| 4 | 7 | | 8 | | 9 | | 10 | | 11 | | 12 | | |
| 5 | | | | | | | | | | | | | |
| 6 | 18 | | 17 | | 16 | | 15 | | 14 | | 13 | | |
| 7 | | | | | | | | | | | | | |
| 8 | 19 | | 20 | | 21 | | 22 | | 23 | | 24 | | |
| 9 | | | | | | | | | | | | | |
| 10 | 30 | | 29 | | 28 | | 27 | | 26 | | 25 | | |
| 11 | | | | | | | | | | | | | |
| 12 | 31 | | 32 | | 33 | | 34 | | 35 | | 36 | | |
| 13 | | | | | | | | | | | | | |

A. Description of original monument and accessories and/or subsequent restoration:

9 - CSR - L. 1 P. 8 - C.P. Tuller - 1900 CWE 1/64 - None
 Set Ironwood post
 Hemlock 14" N32°E 23'
 Elm 5" East 12'



B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

| | |
|---|---|
| <p><u>9</u> - CE 1/16 Cor., Sec. 16, T26N, R13W - Could find no evidence of Tuller position. Set 2" Alum. Cap on 5/8"x 34" Rebar per standard BLM procedure. E-W fence is 5' South.</p> | <p><u>CWE 1/64</u> - NE Cor. of W 1/2 of W 1/2 of N 1/2 of SE 1/4, Sec. 16, T26N, R13W Set 2" Alum. Cap on 5/8"x 34" Rebar per standard BLM procedure. E-W fence is 8.5' South.</p> |
|---|---|

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

| | |
|--|--|
| <p><u>9</u> - 2" Alum. Cap on 5/8"x 34" Rebar N43°W 202.43' to N&T in NE. Side 4" W. Pine N85°W 199.46' to N&T in N. Side 16" S. Maple S44°E 68.60' to N&T in SW. Side 24" S. Maple S39°W 57.46' to N&T in SE. Side 6" W. Pine Set blue Carsonite post 1' NW.</p> | <p><u>CWE 1/64</u> - 2" Alum. Cap on 5/8"x 34" Rebar S40°W 59.31' to N&T in SE. Side 12" B. Cherry N10°W 69.61' to N&T in E. Side 10" W. Pine N35°E 46.44' to N&T in SE. Side Tw. 18" S. Maple N78°E 83.41' to N&T in S. Side 4" W. Pine Set blue Carsonite post 1' NW.</p> |
|--|--|

Signed by: Craig W. McVean Date: 3/29/2000
 Surveyor's Michigan License No.: 39088