

1111 A S 1299

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

LIBER 2 PAGE 249

SHOM	J. C.		
For corners in	<i>≱</i> 1 €		STATE OF 'MICHIGAN
			BENZIE COUNTY
Benzie (County)	Located In: Cor	ner Code #	RECORDED
(County)			
1. Public Land Survey	- T_26N-R_13W	A-3	27 JAN 1999 9:11:54 AM
	T 26N R 14W	M-3	MICHELLE R. GRAY
2. Property Controlling	STR	· ·	REGISTER OF DEEDS
in Section	STR		# PAGES _OVE
3. Miscellaneous	S T R		
Property in Sec.	S TR		Register of Deeds Stamp & File Numb
4. Lot No , F	Recorded Plat		
			A B C D E F G H I J K L M
			1
5. Private Claims			2 6 5 7 4 7 3 7 2 7 1 7
•			3 P-+
L Crain W McVean	in a field survey on July 14, 15	98 do hereby	4 - 7 - 8 - 1 - 9 - 1 - 10 - 11 - 12
I, <u>Craig W. McVean</u> , in a field survey on <u>July 14, 19 98</u> do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points			5
mentioned in lines 1 and 2 abo	ove were in conformance with regulation	ons and rules	6 19 17 16 15 14 13
therefore as required in the cu	irrent manual of survey instructions of	the United	7
States Department of the Inte	rior, Bureau of Land Management or be corner points mentioned in lines 3, 4 a	/ a decree of a	8 19 20 21 22 23 4
Court of Law and for that the	of the Michigan Board of Land Survey	ors or by a	
Decree of a Court of Law; established, re-established, monumented, recovered,			10 30 29 28 27 26 25
found as expressed below:			10-30-29-1-20-1-20-1-20-1
			12 31 32 33 3 3 3 3 3 3 3 3 3 3 3 3 3 3
NOTE: Not more than 2	corners, all in the same town and	I range may be recorded on thi	13 13 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
NOTE: Not more than 2 certificate.	Comers, an in the same town and	range, may be recorded on an	
cerdicate.			
	•		
A. Description of original	monument and accessories and/	or subsequent restoration:	
A-3 & M-3 - GLO - Set p			# 71-6 - Carl Roser - 1971
Beech 10" S39°W 21L			skein (axel) in old fence remains N-S-E
Beech	n 9" N58°W 34L		Ion.& Cedar post
			& ¼ Cor. to North
	of T26N,R13W - Alvin & Austin		
	ct E. from post		ry N22°W 55.9′
	1 6" N32°E 37L		y N43°E 38.3′
Beech	n 10″ S10ºE 34L	- DNK Project i	# 31-93100 ~ Carl Roser - 1981
Description of course	evidence found and/or method ap	unlied in rectoring or recetablish	ning corner
3. Description of corner	evidence round and/or method ap	phied in restoring or reestablish	ang comer.
4.3 & M-3 - Corner comm	on to Sec.'s 6&7, T26N, R13W	and Sec.'s 1&12. T26N.R14W	. FND. Iron wagon skein, (axle),1' long &
tapered end t	to end from 0.10' to 0.25'. FND	, DNR 4" Alum. Cap on 1"x 36	" long Iron Pipe 0.14'S & 0.10'W of skein.
FND. Cedar p	post lying nearby. Accepted the	position of the wagon skein as	the best available evidence of the position
of the origina			
Description of manusma	ent for corner and accessories est	ablished to perpetuate locating	the position of the corner:
. Description of monume	int for comer and accessories est	splistied to beibetdate locating	the position of the comon
A-3 & M-3 – Replace was	on skein & DNR Mon. w/ Benzie	Co. Concrete Monument.	The state of the s
	9' to set N&T in SW. Side 3" B. C		THE OF MICHIGA
	6' to set N&T in E. Side 9" S. Ma		
	B' to set N&T in SE. Side 12" B.		CRAIG W.
N75°E 31.30	O' to set N&T in S. Side Tri14"	5. Maple - scribed 'XBT'	MCVEAN A
	9' to set N&T in S. Side 3" R. M		T AMAGERACIANAL T
	ace of reset 7" Cedar post		
	sonite post 1' SW.	Ratified by Peer Group	
		In accordance with P.	39068 39068
		//	
		Chairman School School	POPESSION
	_	Dale JULY 8 1998	X
\sim .	ar. m. A.	VIA Water Committee Commit	
igned by Orme	W. Mullen	· .	Date 9/30/1998
		0000	- / - /
urvevor's Michigan Licens	e No.	39088	