LAND CORNER RECORDATION CERTIFICATE

	Filing Requ	uirement of Act 74, Micl	h. PA 1970	
For Corners In: Benzie (County)	Located In	Corner Code #		
requirements of PA 74, Mic and 2 above were in conforthe current manual of sur Interior, Bureau of Land Ma corner points mentioned in of the Michigan Board of established, re-established,	Recorded Plat: field survey on April 6, 2005 do he chigan PA of 1970, the corner poin rmance with regulations and rules to vey instructions of the United Stanagement or by a decree of a Cour lines 3, 4 and 5 above were in confictand Surveyors or by a Decremonumented, recovered, found as 2 corners, all in the same tow	the mentioned in lines 1 therefore as required in the Department of the control of Law and/or that the formance with the rules e of a Court of Law; expressed below:	Register of Deeds 3 A B C D E F G 1	Stamp & File Number H
	monument and accessories an r. Sec. Cor. – Alvin & Austin Bur 0 L.		on:	
K2 – ¼ Cor. Common to	evidence found and/or method a Sec. 1 & 2 – No GLO evidence enterline of N-S 2-track is 32' E nal corner.	found. Set Benzie Co. R	emon. Mon. by single propo	rtion to GLO between rees e-establishment of the

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

<u>K2</u> – Stamped 3" Benzie Co. Remon. Brass Cap on ¾" x 36" iron pipe encased in 4" x 36" conc. Cylinder. Set Blue Carsonite Post 1' N S69°W 21.98' to set N & T in S. side 6" J. Pine S8°E 37.28' to set N & T in E. side 6" J. Pine scribed 'XBT' N86°E 48.74' to set N & T in N side 15" Tw. R. Maple scribed 'XBT'

N45°E 70.02' to set N & T in NW side 16" S. Maple scribed 'XBT'

Surveyor's Michigan License No.: 39088

